




Figure 325: Spurious Emissions at Antenna Terminal 16QAM, 1937.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz




Figure 326: Spurious Emissions at Antenna Terminal 16QAM, 1962.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz




Figure 327: Spurious Emissions at Antenna Terminal 16QAM, 1987.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz




Figure 328: Spurious Emissions at Antenna Terminal 16QAM, 1940.0MHz,
B.W. 20MHz, Sub Carrier 15 kHz




Figure 329: Spurious Emissions at Antenna Terminal 16QAM, 1962.5MHz,
B.W. 20MHz, Sub Carrier 15 kHz




Figure 330: Spurious Emissions at Antenna Terminal 16QAM, 1985.0MHz,
B.W. 20MHz, Sub Carrier 15 kHz




Figure 331: Spurious Emissions at Antenna Terminal 16QAM, 1940.0MHz,
B.W. 20MHz, Sub Carrier 30 kHz




Figure 332: Spurious Emissions at Antenna Terminal 16QAM, 1962.5MHz,
B.W. 20MHz, Sub Carrier 30 kHz




Figure 333: Spurious Emissions at Antenna Terminal 16QAM,1985.0MHz,
B.W. 20MHz, Sub Carrier 30 kHz




Figure 334: Spurious Emissions at Antenna Terminal 16QAM, 1940.0MHz,
B.W. 20MHz, Sub Carrier 60 kHz




Figure 335: Spurious Emissions at Antenna Terminal 16QAM, 1962.5MHz,
B.W. 20MHz, Sub Carrier 60 kHz




Figure 336: Spurious Emissions at Antenna Terminal 16QAM, 1985.0MHz,
B.W. 20MHz, Sub Carrier 60 kHz