

Hi Glen.

I would like to confirm that I have a copy of section 90.219 & 22.383 for in-building/booster operation and our boosters comply with these rules.

Best Regards,

David Levy,

Technical Support Manager

Dekolink Wireless Ltd.

16 Bazel St. Qiryat-Arieh Petah-Tikva, Israel, 49510

Tel- 972-3-9180179 Fax-972-3-9180190