

TRENDware International Inc.

3135 Kashiwa street, Torrance, CA 90505, USA

TEL: 1-(310)-891-1100 FAX: 1-(310)-891-1111

41

Federal Communications Commission

7435 Oakland Mills Road

Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: **SI5WCB370A**

To The Commission:

This Change of Identification request applies for a new FCC ID: **S9ZTEW621PC** as established in 47CFR 2.933(b) for a currently approved device. This application by TRENDware will establish a new FCC ID under TRENDware grantee code for purpose of marketing. The original grant to U-MEDIA Communications, Inc. will remain in effect.

An authorization letter by U-MEDIA Communications, Inc. is attached.

Per 2.933(b)

1. The original identification is **SI5WCB370A**.
2. The original grant date is **07/03/2006**.
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.


The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,



Wen Tsai / Sr.Product Manager

TRENDware International Inc.

TEL: 1-(310)-626-6252

FAX: 1-(310)-626-6267

E-mail: w.tsai@trendnet.com