




Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526 -4100
<http://www.cisco.com>

Exhibit : Internal Photos

Model Number: CP-8821
FCC ID: LDK88211296
IC: 2461B-88211296

: Internal Views

LCD and Keypad are assembled first, then main PCB, ... so you could not remove LCD and Keypad first to show main PCB.




Keypad and housing picture

Keypad top



Keypad bottom




This keypad connector
to main PCB keypad
connector

FOXCONN

LCD Module:



Keypad connection:





Key pad connect to this connector

LCD connection:



Top side of PCBA





BOTTOM SIDE of PCBA

