

Date: Dec 08, 2024

### **Justification for Re-use of Radio Test Results**

We, KoreLock Inc, believe that the conducted signal test data on original reports provided by the Laird Technologies FCC ID: SQGBL654 Report# FR813002 on 29<sup>th</sup> Jun 2018, ESPRESSIF SYSTEMS (SHANGHAI) CO., LTD FCC ID: 2AC7Z-ESPS2MINI2 Report# FR262713 on 10<sup>th</sup> Nov 2022 & PassiveBolt, Inc.FCC ID: 2AV6C-CRCM1101B1 on 4<sup>th</sup> Dec 2024 can be re-used for the following reasons:

1. Applicant has built in the radio module according to the specific radio module integration guides.
2. No changes have been made on radio module.
3. Re-test the conducted power for spot check verification, the radiated spurious emission, and reevaluated the RF Exposure.

Also, we have disabled the 801.15.4 proprietary protocol in the BLE module.

A handwritten signature in black ink, appearing to read 'R. Goff'.

By Robert Goff

Title: VP, Product