



November 4, 2021

**Federal Communications Commission**

7435 Oakland Mills Road  
Columbia, MD 21046

**Re: Request Change in Identification**

Dear Examiner,

This change of identification request applies for FCC ID: **N7NRC76B** as established in 47CFR 2.933(b) for a currently approved device. This application by DMS-Service LLC will establish a new FCC ID: **2A3KO-RC7611** for purpose of marketing. The original grant to Sierra Wireless will remain in effect per 2.933(b).

1. The original identification is FCC ID: N7NRC76B
2. The original grant date is 02/05/2020
3. The equipment is electrically identical, only application and FCC ID are different
4. The original test results are applicable and representative of this changed device
5. Exterior photographs are included in this application

Best regards,

*Lynda Cole*

Name: Lynda Cole  
Title: Owner/Member  
On Behalf of dms-service llc

Phone: (540) 212-7000