

## Request for Class II Permissive Change

**FCC ID: 2A64B-DLX23**


**Data: June 12, 2023**

**TO: Federal Communication Commission**

Please be notified that we, the undersigned, Ecovacs Home Service Robotics Co., Ltd. declare that the reasons for this Class II permissive change are as below:

1. Added alternative construction with one or two magnet rings;


Description: alternative construction with two magnet rings





Description: alternative construction with one magnet rings



2. Added alternative photo with different colour;



3. Added photos with different Shielding cover and PCB Layout;  
The original mainboard



The new mainboard



Ecovacs Home Service Robotics Co., Ltd.

No.518 Songwei Road, Wusongjiang industry Park, Guoxiang Street, Wuzhong District,  
Suzhou, Jiangsu, China.

**Thank you.**

**Sincerely,**

*Alix Liu*

---

**Alix Liu / Compliance Manager**  
**Ecovacs Home Service Robotics Co., Ltd.**  
**Tel: 0512-67072006**  
**Email: [alix.liu@ecovacs.com](mailto:alix.liu@ecovacs.com)**