





Band41-20MHz-QPSK-41040-1RB#0-Range2:1000~27000MHz



Band41-20MHz-16QAM-40440-1RB#0-Range1:30~1000MHz



Band41-20MHz-16QAM-40440-1RB#0-Range2:1000~27000MHz

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com




Hotline

400-003-0500


www.anbotek.com



Band41-20MHz-16QAM-40690-1RB#0-Range1:30~1000MHz



Band41-20MHz-16QAM-40690-1RB#0-Range2:1000~27000MHz




Band41-20MHz-16QAM-41040-1RB#0-Range1:30~1000MHz

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline
400-003-0500
www.anbotek.com



Band41-20MHz-16QAM-41040-1RB#0-Range2:1000~27000MHz



Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

Appendix F: Frequency Stability VS Voltage

Test Result

Voltage										
Band	Bandwidth	Modulation	Channel	RB Configuration	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band4_1	5MHz	QPSK	40365	25RB#0	VL	NT	-21.17	-0.008245	±2.5	PASS
Band4_1	5MHz	QPSK	40365	25RB#0	VN	NT	-22.54	-0.008779	±2.5	PASS
Band4_1	5MHz	QPSK	40365	25RB#0	VH	NT	-13.75	-0.005355	±2.5	PASS
Band4_1	5MHz	QPSK	40690	25RB#0	VL	NT	-6.39	-0.002458	±2.5	PASS
Band4_1	5MHz	QPSK	40690	25RB#0	VN	NT	29.34	0.011285	±2.5	PASS
Band4_1	5MHz	QPSK	40690	25RB#0	VH	NT	-3.72	-0.001431	±2.5	PASS
Band4_1	5MHz	QPSK	41115	25RB#0	VL	NT	-30.31	-0.011470	±2.5	PASS
Band4_1	5MHz	QPSK	41115	25RB#0	VN	NT	5.44	0.002059	±2.5	PASS
Band4_1	5MHz	QPSK	41115	25RB#0	VH	NT	-14.78	-0.005593	±2.5	PASS
Band4_1	5MHz	16QAM	40365	25RB#0	VL	NT	-7.78	-0.003030	±2.5	PASS
Band4_1	5MHz	16QAM	40365	25RB#0	VN	NT	-11.19	-0.004358	±2.5	PASS
Band4_1	5MHz	16QAM	40365	25RB#0	VH	NT	5.75	0.002240	±2.5	PASS
Band4_1	5MHz	16QAM	40690	25RB#0	VL	NT	-43.66	-0.016792	±2.5	PASS
Band4_1	5MHz	16QAM	40690	25RB#0	VN	NT	-39.94	-0.015362	±2.5	PASS
Band4_1	5MHz	16QAM	40690	25RB#0	VH	NT	-40.27	-0.015488	±2.5	PASS
Band4_1	5MHz	16QAM	41115	25RB#0	VL	NT	-297.17	-0.112458	±2.5	PASS
Band4_1	5MHz	16QAM	41115	25RB#0	VN	NT	-323.01	-0.122237	±2.5	PASS
Band4_1	5MHz	16QAM	41115	25RB#0	VH	NT	-271.10	-0.102592	±2.5	PASS

Shenzhen Anbotech Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com



Hotline

400-003-0500

www.anbotech.com

1										
Band4 1	10MHz	QPSK	40365	50RB#0	VL	NT	-3.85	-0.001500	±2.5	PASS
Band4 1	10MHz	QPSK	40365	50RB#0	VN	NT	-16.65	-0.006485	±2.5	PASS
Band4 1	10MHz	QPSK	40365	50RB#0	VH	NT	-9.76	-0.003801	±2.5	PASS
Band4 1	10MHz	QPSK	40690	50RB#0	VL	NT	-11.14	-0.004285	±2.5	PASS
Band4 1	10MHz	QPSK	40690	50RB#0	VN	NT	9.17	0.003527	±2.5	PASS
Band4 1	10MHz	QPSK	40690	50RB#0	VH	NT	-6.94	-0.002669	±2.5	PASS
Band4 1	10MHz	QPSK	41115	50RB#0	VL	NT	-11.82	-0.004473	±2.5	PASS
Band4 1	10MHz	QPSK	41115	50RB#0	VN	NT	5.89	0.002229	±2.5	PASS
Band4 1	10MHz	QPSK	41115	50RB#0	VH	NT	-2.96	-0.001120	±2.5	PASS
Band4 1	10MHz	16QAM	40365	50RB#0	VL	NT	-13.70	-0.005336	±2.5	PASS
Band4 1	10MHz	16QAM	40365	50RB#0	VN	NT	-3.20	-0.001246	±2.5	PASS
Band4 1	10MHz	16QAM	40365	50RB#0	VH	NT	-16.97	-0.006610	±2.5	PASS
Band4 1	10MHz	16QAM	40690	50RB#0	VL	NT	-8.15	-0.003135	±2.5	PASS
Band4 1	10MHz	16QAM	40690	50RB#0	VN	NT	-10.66	-0.004100	±2.5	PASS
Band4 1	10MHz	16QAM	40690	50RB#0	VH	NT	-9.31	-0.003581	±2.5	PASS
Band4 1	10MHz	16QAM	41115	50RB#0	VL	NT	-6.27	-0.002373	±2.5	PASS
Band4 1	10MHz	16QAM	41115	50RB#0	VN	NT	3.55	0.001343	±2.5	PASS
Band4 1	10MHz	16QAM	41115	50RB#0	VH	NT	-14.00	-0.005298	±2.5	PASS
Band4 1	15MHz	QPSK	40415	75RB#0	VL	NT	-22.40	-0.008707	±2.5	PASS
Band4 1	15MHz	QPSK	40415	75RB#0	VN	NT	-19.14	-0.007440	±2.5	PASS
Band4 1	15MHz	QPSK	40415	75RB#0	VH	NT	-20.94	-0.008140	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

Band4 1	15MHz	QPSK	40690	75RB#0	VL	NT	-13.13	-0.005050	±2.5	PASS
Band4 1	15MHz	QPSK	40690	75RB#0	VN	NT	9.26	0.003562	±2.5	PASS
Band4 1	15MHz	QPSK	40690	75RB#0	VH	NT	6.85	0.002635	±2.5	PASS
Band4 1	15MHz	QPSK	41065	75RB#0	VL	NT	5.48	0.002078	±2.5	PASS
Band4 1	15MHz	QPSK	41065	75RB#0	VN	NT	5.52	0.002093	±2.5	PASS
Band4 1	15MHz	QPSK	41065	75RB#0	VH	NT	-4.71	-0.001786	±2.5	PASS
Band4 1	15MHz	16QAM	40415	75RB#0	VL	NT	-7.30	-0.002838	±2.5	PASS
Band4 1	15MHz	16QAM	40415	75RB#0	VN	NT	-14.99	-0.005827	±2.5	PASS
Band4 1	15MHz	16QAM	40415	75RB#0	VH	NT	-12.17	-0.004731	±2.5	PASS
Band4 1	15MHz	16QAM	40690	75RB#0	VL	NT	-8.48	-0.003262	±2.5	PASS
Band4 1	15MHz	16QAM	40690	75RB#0	VN	NT	-6.15	-0.002365	±2.5	PASS
Band4 1	15MHz	16QAM	40690	75RB#0	VH	NT	-9.34	-0.003592	±2.5	PASS
Band4 1	15MHz	16QAM	41065	75RB#0	VL	NT	-2.35	-0.000891	±2.5	PASS
Band4 1	15MHz	16QAM	41065	75RB#0	VN	NT	-7.11	-0.002696	±2.5	PASS
Band4 1	15MHz	16QAM	41065	75RB#0	VH	NT	-11.07	-0.004197	±2.5	PASS
Band4 1	20MHz	QPSK	40440	100RB#0	VL	NT	-17.94	-0.006967	±2.5	PASS
Band4 1	20MHz	QPSK	40440	100RB#0	VN	NT	-20.30	-0.007883	±2.5	PASS
Band4 1	20MHz	QPSK	40440	100RB#0	VH	NT	-18.21	-0.007072	±2.5	PASS
Band4 1	20MHz	QPSK	40690	100RB#0	VL	NT	-8.47	-0.003258	±2.5	PASS
Band4 1	20MHz	QPSK	40690	100RB#0	VN	NT	12.63	0.004858	±2.5	PASS
Band4 1	20MHz	QPSK	40690	100RB#0	VH	NT	-9.04	-0.003477	±2.5	PASS
Band4 1	20MHz	QPSK	41040	100RB#0	VL	NT	-19.13	-0.007260	±2.5	PASS

Shenzhen Anbotech Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com



Hotline

400-003-0500

www.anbotech.com

1										
Band4 1	20MHz	QPSK	41040	100RB#0	VN	NT	-10.11	-0.003837	±2.5	PASS
Band4 1	20MHz	QPSK	41040	100RB#0	VH	NT	15.44	0.005860	±2.5	PASS
Band4 1	20MHz	16QAM	40440	100RB#0	VL	NT	3.29	0.001278	±2.5	PASS
Band4 1	20MHz	16QAM	40440	100RB#0	VN	NT	-13.59	-0.005278	±2.5	PASS
Band4 1	20MHz	16QAM	40440	100RB#0	VH	NT	3.42	0.001328	±2.5	PASS
Band4 1	20MHz	16QAM	40690	100RB#0	VL	NT	-13.38	-0.005146	±2.5	PASS
Band4 1	20MHz	16QAM	40690	100RB#0	VN	NT	-12.32	-0.004738	±2.5	PASS
Band4 1	20MHz	16QAM	40690	100RB#0	VH	NT	-16.11	-0.006196	±2.5	PASS
Band4 1	20MHz	16QAM	41040	100RB#0	VL	NT	-8.47	-0.003214	±2.5	PASS
Band4 1	20MHz	16QAM	41040	100RB#0	VN	NT	-13.78	-0.005230	±2.5	PASS
Band4 1	20MHz	16QAM	41040	100RB#0	VH	NT	-13.65	-0.005180	±2.5	PASS

Shenzhen Anbotech Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com



Hotline

400-003-0500

www.anbotech.com

Appendix G: Frequency Stability VS Temperature

Test Result

Temperature										
Band	Bandwidth	Modulation	Channel	RB Configuration	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band4_1	5MHz	QPSK	40365	25RB#0	NV	-30	-4.28	-0.001667	±2.5	PASS
Band4_1	5MHz	QPSK	40365	25RB#0	NV	-20	11.23	0.004374	±2.5	PASS
Band4_1	5MHz	QPSK	40365	25RB#0	NV	0	-7.11	-0.002769	±2.5	PASS
Band4_1	5MHz	QPSK	40365	25RB#0	NV	10	-9.37	-0.003649	±2.5	PASS
Band4_1	5MHz	QPSK	40365	25RB#0	NV	20	5.22	0.002033	±2.5	PASS
Band4_1	5MHz	QPSK	40690	25RB#0	NV	-30	-14.25	-0.005481	±2.5	PASS
Band4_1	5MHz	QPSK	40690	25RB#0	NV	-20	-7.10	-0.002731	±2.5	PASS
Band4_1	5MHz	QPSK	40690	25RB#0	NV	0	-8.58	-0.003300	±2.5	PASS
Band4_1	5MHz	QPSK	40690	25RB#0	NV	10	-19.53	-0.007512	±2.5	PASS
Band4_1	5MHz	QPSK	40690	25RB#0	NV	20	-31.89	-0.012265	±2.5	PASS
Band4_1	5MHz	QPSK	41115	25RB#0	NV	-30	8.17	0.003092	±2.5	PASS
Band4_1	5MHz	QPSK	41115	25RB#0	NV	-20	26.69	0.010100	±2.5	PASS
Band4_1	5MHz	QPSK	41115	25RB#0	NV	0	32.72	0.012382	±2.5	PASS
Band4_1	5MHz	QPSK	41115	25RB#0	NV	10	44.95	0.017010	±2.5	PASS
Band4_1	5MHz	QPSK	41115	25RB#0	NV	20	75.73	0.028658	±2.5	PASS
Band4_1	5MHz	16QAM	40365	25RB#0	NV	-30	-5.34	-0.002080	±2.5	PASS
Band4_1	5MHz	16QAM	40365	25RB#0	NV	-20	-6.57	-0.002559	±2.5	PASS
Band4_1	5MHz	16QAM	40365	25RB#0	NV	0	-13.83	-0.005387	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline
400-003-0500
www.anbotek.com

Band4 1	5MHz	16QAM	40365	25RB#0	NV	10	-7.70	-0.002999	±2.5	PASS
Band4 1	5MHz	16QAM	40365	25RB#0	NV	20	-19.73	-0.007685	±2.5	PASS
Band4 1	5MHz	16QAM	40690	25RB#0	NV	-30	-41.16	-0.015831	±2.5	PASS
Band4 1	5MHz	16QAM	40690	25RB#0	NV	-20	-35.92	-0.013815	±2.5	PASS
Band4 1	5MHz	16QAM	40690	25RB#0	NV	0	-25.59	-0.009842	±2.5	PASS
Band4 1	5MHz	16QAM	40690	25RB#0	NV	10	-28.85	-0.011096	±2.5	PASS
Band4 1	5MHz	16QAM	40690	25RB#0	NV	20	-38.68	-0.014877	±2.5	PASS
Band4 1	5MHz	16QAM	41115	25RB#0	NV	-30	-248.92	-0.094199	±2.5	PASS
Band4 1	5MHz	16QAM	41115	25RB#0	NV	-20	-236.95	-0.089669	±2.5	PASS
Band4 1	5MHz	16QAM	41115	25RB#0	NV	0	-222.43	-0.084174	±2.5	PASS
Band4 1	5MHz	16QAM	41115	25RB#0	NV	10	-234.09	-0.088587	±2.5	PASS
Band4 1	5MHz	16QAM	41115	25RB#0	NV	20	-226.65	-0.085771	±2.5	PASS
Band4 1	10MHz	QPSK	40365	50RB#0	NV	-30	-13.39	-0.005215	±2.5	PASS
Band4 1	10MHz	QPSK	40365	50RB#0	NV	-20	-14.91	-0.005807	±2.5	PASS
Band4 1	10MHz	QPSK	40365	50RB#0	NV	0	-4.13	-0.001609	±2.5	PASS
Band4 1	10MHz	QPSK	40365	50RB#0	NV	10	-10.73	-0.004179	±2.5	PASS
Band4 1	10MHz	QPSK	40365	50RB#0	NV	20	-5.51	-0.002146	±2.5	PASS
Band4 1	10MHz	QPSK	40690	50RB#0	NV	-30	3.23	0.001242	±2.5	PASS
Band4 1	10MHz	QPSK	40690	50RB#0	NV	-20	-10.74	-0.004131	±2.5	PASS
Band4 1	10MHz	QPSK	40690	50RB#0	NV	0	-3.62	-0.001392	±2.5	PASS
Band4 1	10MHz	QPSK	40690	50RB#0	NV	10	-13.18	-0.005069	±2.5	PASS
Band4 1	10MHz	QPSK	40690	50RB#0	NV	20	-7.85	-0.003019	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

1										
Band4 1	10MHz	QPSK	41115	50RB#0	NV	-30	-8.50	-0.003217	±2.5	PASS
Band4 1	10MHz	QPSK	41115	50RB#0	NV	-20	7.80	0.002952	±2.5	PASS
Band4 1	10MHz	QPSK	41115	50RB#0	NV	0	4.12	0.001559	±2.5	PASS
Band4 1	10MHz	QPSK	41115	50RB#0	NV	10	-7.68	-0.002906	±2.5	PASS
Band4 1	10MHz	QPSK	41115	50RB#0	NV	20	-5.85	-0.002214	±2.5	PASS
Band4 1	10MHz	16QAM	40365	50RB#0	NV	-30	-5.88	-0.002290	±2.5	PASS
Band4 1	10MHz	16QAM	40365	50RB#0	NV	-20	-10.44	-0.004066	±2.5	PASS
Band4 1	10MHz	16QAM	40365	50RB#0	NV	0	-16.54	-0.006442	±2.5	PASS
Band4 1	10MHz	16QAM	40365	50RB#0	NV	10	-4.81	-0.001873	±2.5	PASS
Band4 1	10MHz	16QAM	40365	50RB#0	NV	20	-5.61	-0.002185	±2.5	PASS
Band4 1	10MHz	16QAM	40690	50RB#0	NV	-30	-11.57	-0.004450	±2.5	PASS
Band4 1	10MHz	16QAM	40690	50RB#0	NV	-20	-6.98	-0.002685	±2.5	PASS
Band4 1	10MHz	16QAM	40690	50RB#0	NV	0	-4.08	-0.001569	±2.5	PASS
Band4 1	10MHz	16QAM	40690	50RB#0	NV	10	-9.66	-0.003715	±2.5	PASS
Band4 1	10MHz	16QAM	40690	50RB#0	NV	20	-10.03	-0.003858	±2.5	PASS
Band4 1	10MHz	16QAM	41115	50RB#0	NV	-30	-12.69	-0.004802	±2.5	PASS
Band4 1	10MHz	16QAM	41115	50RB#0	NV	-20	-10.06	-0.003807	±2.5	PASS
Band4 1	10MHz	16QAM	41115	50RB#0	NV	0	-12.06	-0.004564	±2.5	PASS
Band4 1	10MHz	16QAM	41115	50RB#0	NV	10	-9.34	-0.003535	±2.5	PASS
Band4 1	10MHz	16QAM	41115	50RB#0	NV	20	-5.98	-0.002263	±2.5	PASS
Band4 1	15MHz	QPSK	40415	75RB#0	NV	-30	-10.40	-0.004043	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

Band4 1	15MHz	QPSK	40415	75RB#0	NV	-20	-17.27	-0.006713	±2.5	PASS
Band4 1	15MHz	QPSK	40415	75RB#0	NV	0	-18.75	-0.007289	±2.5	PASS
Band4 1	15MHz	QPSK	40415	75RB#0	NV	10	-14.29	-0.005555	±2.5	PASS
Band4 1	15MHz	QPSK	40415	75RB#0	NV	20	-16.06	-0.006243	±2.5	PASS
Band4 1	15MHz	QPSK	40690	75RB#0	NV	-30	6.34	0.002438	±2.5	PASS
Band4 1	15MHz	QPSK	40690	75RB#0	NV	-20	-8.83	-0.003396	±2.5	PASS
Band4 1	15MHz	QPSK	40690	75RB#0	NV	0	-10.01	-0.003850	±2.5	PASS
Band4 1	15MHz	QPSK	40690	75RB#0	NV	10	-5.55	-0.002135	±2.5	PASS
Band4 1	15MHz	QPSK	40690	75RB#0	NV	20	-2.80	-0.001077	±2.5	PASS
Band4 1	15MHz	QPSK	41065	75RB#0	NV	-30	-6.65	-0.002521	±2.5	PASS
Band4 1	15MHz	QPSK	41065	75RB#0	NV	-20	4.99	0.001892	±2.5	PASS
Band4 1	15MHz	QPSK	41065	75RB#0	NV	0	-4.33	-0.001642	±2.5	PASS
Band4 1	15MHz	QPSK	41065	75RB#0	NV	10	-5.49	-0.002082	±2.5	PASS
Band4 1	15MHz	QPSK	41065	75RB#0	NV	20	-7.14	-0.002707	±2.5	PASS
Band4 1	15MHz	16QAM	40415	75RB#0	NV	-30	-9.47	-0.003681	±2.5	PASS
Band4 1	15MHz	16QAM	40415	75RB#0	NV	-20	-17.82	-0.006927	±2.5	PASS
Band4 1	15MHz	16QAM	40415	75RB#0	NV	0	-6.79	-0.002639	±2.5	PASS
Band4 1	15MHz	16QAM	40415	75RB#0	NV	10	4.96	0.001928	±2.5	PASS
Band4 1	15MHz	16QAM	40415	75RB#0	NV	20	-7.18	-0.002791	±2.5	PASS
Band4 1	15MHz	16QAM	40690	75RB#0	NV	-30	-18.53	-0.007127	±2.5	PASS
Band4 1	15MHz	16QAM	40690	75RB#0	NV	-20	-19.14	-0.007362	±2.5	PASS
Band4 1	15MHz	16QAM	40690	75RB#0	NV	0	-14.09	-0.005419	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

1										
Band4 1	15MHz	16QAM	40690	75RB#0	NV	10	-16.14	-0.006208	±2.5	PASS
Band4 1	15MHz	16QAM	40690	75RB#0	NV	20	-9.73	-0.003742	±2.5	PASS
Band4 1	15MHz	16QAM	41065	75RB#0	NV	-30	-16.91	-0.006411	±2.5	PASS
Band4 1	15MHz	16QAM	41065	75RB#0	NV	-20	-8.57	-0.003249	±2.5	PASS
Band4 1	15MHz	16QAM	41065	75RB#0	NV	0	-11.64	-0.004413	±2.5	PASS
Band4 1	15MHz	16QAM	41065	75RB#0	NV	10	-6.59	-0.002499	±2.5	PASS
Band4 1	15MHz	16QAM	41065	75RB#0	NV	20	-5.62	-0.002131	±2.5	PASS
Band4 1	20MHz	QPSK	40440	100RB#0	NV	-30	-18.71	-0.007266	±2.5	PASS
Band4 1	20MHz	QPSK	40440	100RB#0	NV	-20	-16.59	-0.006443	±2.5	PASS
Band4 1	20MHz	QPSK	40440	100RB#0	NV	0	-13.55	-0.005262	±2.5	PASS
Band4 1	20MHz	QPSK	40440	100RB#0	NV	10	-17.17	-0.006668	±2.5	PASS
Band4 1	20MHz	QPSK	40440	100RB#0	NV	20	-9.67	-0.003755	±2.5	PASS
Band4 1	20MHz	QPSK	40690	100RB#0	NV	-30	-7.47	-0.002873	±2.5	PASS
Band4 1	20MHz	QPSK	40690	100RB#0	NV	-20	-8.47	-0.003258	±2.5	PASS
Band4 1	20MHz	QPSK	40690	100RB#0	NV	0	-8.63	-0.003319	±2.5	PASS
Band4 1	20MHz	QPSK	40690	100RB#0	NV	10	-12.22	-0.004700	±2.5	PASS
Band4 1	20MHz	QPSK	40690	100RB#0	NV	20	-9.50	-0.003654	±2.5	PASS
Band4 1	20MHz	QPSK	41040	100RB#0	NV	-30	-7.20	-0.002732	±2.5	PASS
Band4 1	20MHz	QPSK	41040	100RB#0	NV	-20	-6.29	-0.002387	±2.5	PASS
Band4 1	20MHz	QPSK	41040	100RB#0	NV	0	-6.72	-0.002550	±2.5	PASS
Band4 1	20MHz	QPSK	41040	100RB#0	NV	10	8.25	0.003131	±2.5	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

Band4 1	20MHz	QPSK	41040	100RB#0	NV	20	-5.56	-0.002110	±2.5	PASS
Band4 1	20MHz	16QAM	40440	100RB#0	NV	-30	-11.73	-0.004555	±2.5	PASS
Band4 1	20MHz	16QAM	40440	100RB#0	NV	-20	-14.85	-0.005767	±2.5	PASS
Band4 1	20MHz	16QAM	40440	100RB#0	NV	0	-16.85	-0.006544	±2.5	PASS
Band4 1	20MHz	16QAM	40440	100RB#0	NV	10	-14.45	-0.005612	±2.5	PASS
Band4 1	20MHz	16QAM	40440	100RB#0	NV	20	-16.58	-0.006439	±2.5	PASS
Band4 1	20MHz	16QAM	40690	100RB#0	NV	-30	-11.06	-0.004254	±2.5	PASS
Band4 1	20MHz	16QAM	40690	100RB#0	NV	-20	-17.35	-0.006673	±2.5	PASS
Band4 1	20MHz	16QAM	40690	100RB#0	NV	0	-14.33	-0.005512	±2.5	PASS
Band4 1	20MHz	16QAM	40690	100RB#0	NV	10	-6.29	-0.002419	±2.5	PASS
Band4 1	20MHz	16QAM	40690	100RB#0	NV	20	-5.95	-0.002288	±2.5	PASS
Band4 1	20MHz	16QAM	41040	100RB#0	NV	-30	-31.27	-0.011867	±2.5	PASS
Band4 1	20MHz	16QAM	41040	100RB#0	NV	-20	-7.37	-0.002797	±2.5	PASS
Band4 1	20MHz	16QAM	41040	100RB#0	NV	0	-13.79	-0.005233	±2.5	PASS
Band4 1	20MHz	16QAM	41040	100RB#0	NV	10	-6.84	-0.002596	±2.5	PASS
Band4 1	20MHz	16QAM	41040	100RB#0	NV	20	-13.05	-0.004953	±2.5	PASS

---End---

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com