Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Date: June 28, 2017

Internal Photos

FCC ID: PY7-46331W

Without external cosmetic parts





(Front Side)



(Rear Side)





(Left Side)





(Bottom Side)



4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Without internal plate



(Front Side)









(Bottom Side)



4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Without Panel and Battery

(Top Side)



(Front Side)





(Rear Side)



(Left Side)





(Bottom Side)

Sony Mobile Communications, Inc.


4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.


Without PBA

(Top Side/Bottom Side Photo is same as p.10)



Antenna location

*Zoom up photo from above Rear Side and Left Side photo.





4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Without Head and Base block

(Top Side)



(Front Side)

(Front side)

(Right Side)



(Rear Side)



(Left Side)





(Bottom Side)

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Base block

(Top Side)



(Front Side)

(Holl Glas)

(Right Side)



(Rear Side)



(Left Side)





(Bottom Side)



4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks


This document is managed in Infodoc.


Base block without external parts

(Top Side)



(Front Side)





(SW PBA block)

(Rear Side)



(Left Side)





(Bottom Side)

Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

Head block

(Top Side)



(Front Side)



(Right Side)



(Internal PCB)

(Rear Side)



(Left Side)





(Bottom Side)

Sony Mobile Communications, Inc.


4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

PBA Photo





(AL PBA B-side)




(Batt PBA A-side)



(Batt PBA B-side)



(BS PBA A-side)



(BS PBA B-side)



Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.







(ELED PBA B-side)



(HD PBA A-side)



(HD PBA B-side)



(KS PBA A-side)



(KS PBA B-side)



Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.





(LED PBA B-side)



(Motor PBA A-side)



(Motor PBA B-side)



(Main PBA A-side)



(Main PBA B-side)



Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks

This document is managed in Infodoc.

(Main PBA A-side without plate)




(Main PBA B-side without plate)



(SCU PBA A-side)



(SCU PBA B-side)



(SW PBA A-side)



(SW PBA B-side)



Sony Mobile Communications, Inc.

4-12-3 Higashi-shinagawa, Shinagawa-ku, Tokyo, 140-0002, Japan

Remarks
This document is managed in Infodoc.

Panel



Battery





It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.