

INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16060748HKG-002

Equipment Photographs

Model : 1947

(Internal)

