US Tech Test Report:

FCC ID: IC:

Test Report Number: Issue Date:

Customer: Model:

FCC Part 90/RSS 131 Certification

2AKSM-SAFE1 22303-SAFE1

17-0001

March 20, 2017 Safe-Com Wireless SAFE 1000

INTERNAL PHOTOGRAPHS



Figure 1. Inside Enclosure

(Note: Each RF Card Inside is Identical)

Customer:

Model:




Figure 2. RF Card Removed

Customer:

Model:




Figure 3. RF Card with Shield in Place

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:




Figure 4. Front of RF Card

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:




Figure 5. Back of RF Card

Customer:

Model:

Figure 6. RF Card Solder Side

Customer:

Model:

Figure 7. RF Card Component Side (Shield Removed)

Model:




Figure 8. Daughter Card 1, Front and Back

 US Tech Test Report:
 FCC Part 90/RSS 131 Certification

 FCC ID:
 2AKSM-SAFE1

 IC:
 22303-SAFE1

 Test Report Number:
 17-0001

 Issue Date:
 March 20, 2017

 Customer:
 Safe-Com Wireless

 Model:
 SAFE 1000




Figure 9. Daughter Card 2, Front

Model:




Figure 10. Daughter Card 2, Back