



20MHz_Low_QPSK_1@0




ProjectNo.:2402X51137E-RF Tester:Karl Liang
 Date: 20.SEP.2024 13:27:44

20MHz_Low_QPSK_100@0




ProjectNo.:2402X51137E-RF Tester:Karl Liang
 Date: 20.SEP.2024 13:27:58

20MHz_Low_16QAM_1@0




ProjectNo.:2402X51137E-RF Tester:Karl Liang
 Date: 20.SEP.2024 13:28:12

20MHz_Low_16QAM_100@0




ProjectNo.:2402X51137E-RF Tester:Karl Liang
 Date: 20.SEP.2024 13:28:26

20MHz_High_QPSK_1@99




ProjectNo.:2402X51137E-RF Tester:Karl Liang
 Date: 20.SEP.2024 13:28:59

20MHz_High_QPSK_100@0



ProjectNo.:2402X51137E-RF Tester:Karl Liang
 Date: 20.SEP.2024 13:29:22


20MHz_High_16QAM_1@99



ProjectNo.:2402X51137E-RF Tester:Karl Liang

Date: 20.SEP.2024 13:29:36

20MHz_High_16QAM_100@0



ProjectNo.:2402X51137E-RF Tester:Karl Liang

Date: 20.SEP.2024 13:29:50


Spurious Emissions at Antenna Terminal

FCC Part 22H

B5 , Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.SEP.2024 23:27:52

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.SEP.2024 23:28:14

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.SEP.2024 23:28:36

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 20.SEP.2024 00:11:35

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.SEP.2024 23:30:01

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.SEP.2024 23:30:26

5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:30:53

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 20.SEP.2024 00:11:56

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:32:18

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:32:46

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:33:12

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 20.SEP.2024 00:12:20

FCC Part 27

B7 , Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:34:49

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:35:52

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:37:20

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:45:45

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 20.SEP.2024 00:13:01

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Teeter:Karl Liang
Date: 19.SEP.2024 23:53:17

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.8EP.2024 23:53:57

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.8EP.2024 23:54:37

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.8EP.2024 23:55:18

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.8EP.2024 23:56:03

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.8EP.2024 23:56:56

20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2402X51137E-RF Tester:Karl Liang
Date: 19.8EP.2024 23:57:38