

INTERTEK TESTING SERVICES

Report No.: 0408487  
Model No.: 14104

hp

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement MKB 32.250 msec

REF -10.0 dBm

AT 10 dB


- .03 dB

PEAK

LOG

10

dB/



Tested By: *[Signature]*  
(*Kevin Wang*)

Date: 14/5/04

Checked By: *[Signature]*  
(*Barry Chan*)

Date: 19/5/04

Test Result : Pass / Fail / *NA*

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

INTERTEK TESTING SERVICES

Report No.: C905987  
Model No.: 14104

hp


Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement MKB 32.175 msec

REF -10.0 dBm

AT 10 dB

.02 dB

PEAK  
LOG  
10  
dB/



Tested By: (Signature)

Date: 14/5/04

Checked By: (Signature)  
(Anthony Chan)

Date: 17/5/04

Test Result : Pass / Fail (NA)

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 45.0 msec

INTERTEK TESTING SERVICES

Report No.: 0708487  
Model No.: 14104

hp

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement MKR 1.0120 msec

REF -10.0 dBm

AT 10 dB


- .56 dB

PEAK

LOG

10

dB/



WA SB

SC LS

CORR

Tested By:

*(Signature)*  
(Kumar Garg)

Date:

14/5/04

Checked By:

*(Signature)*  
(Anthony Chao)

Date:

19/5/04

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 45.0 msec

INTERTEK TESTING SERVICES

Report No.: 0408487  
Model No.: 14104

hp

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement MKB 450.00  $\mu$ sec

REF -10.0 dBm

AT 10 dB


- .56 dB

PEAK

LOG

10

dB/



WA SB

SC LS

CORR

Tested By: (Signature)

Date: 14/5/04

Checked By: (Signature)  
(Anthony Chan)

Date: 19/5/04

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 45.0 msec