

b mobile HK Limited  
Flat 18; 14/F Block 1; Golden Industrial Building; 16-26 Kwai Tak Street; Kwai Chung; New  
Territories, HONG KONG, China  
TEL.: 852-2728 7886 FAX: 852-2728 0468


## Attestation Letter

February 4, 2016

To:  
Federal Communications Commission  
Office of Engineering and Technology Laboratory Division  
7435 Oakland Mills Rd  
Columbia MD 21046-1609  
Phone: +1-301-362-3000  
Fax: +1-301-362-3290

Dear Sir or Madam:

The RF chip, model MT6572, installed in FCC ID: ZSW-30-023, product name: Mobile  
Phone, model number: AX675, AX670 supports HSPA+ functions. For use in the US this  
chip will not support/enable the HSPA+ function. The HSPA+ function has been shielded by the  
manufacturer using the software.

Best Regards  
*For and on behalf of*  
**b mobile HK Limited**  
Signature:   
KA SHING LAM  
DIRECTOR .....  
*Authorized Signature(s)*