

Uniden America Corporation
6225 N State Highway 161.
Suite 300
Irving, TX 75038
817-858-3300
Fax: 817-858-3333



Date: December 15, 2020

To: TIMCO ENGINEERING, INC., An IIA Company
849 NW State Road 45
Newberry, Florida 32669

Subject: FCC Class II Permissive Change for
HVIN: BCD996P2, FCC ID: AMWUB360, IC: 513-UB360
Original FCC Grant Date: 05/13/2009
Original ISED Certification Date: 01/16/2015
Applicant: Uniden America Corporation

This is to request a Class II Permissive Change for HVIN: BCD996P2, FCC ID: AMWUB360 that was originally granted on 05/13/2009 and the ISED Certification IC: 513C-UB360 that was issued on 01/16/2015.

The major changes filed under this application are:

- Updated PLL circuits:
 - PLL IC/Buffer Amp: MB15F72/UPC274 (EOL) to LMX2485/BGA2802
 - PLL IC (1st Local): 1/2 of MB15F63(EOL)+UPC2757(EOL) to RFFC5072+MO0376+BGA2803
 - PLL IC (2nd Local): 2/2 of MB15F63 (EOL) to MCD2926

Note: MB15F63 contains two PLL in one package.

Regards,

A handwritten signature in blue ink, appearing to read "Paul Roby", written over the printed name and title.

Paul Roby
Manager, Regulatory and Quality
Uniden America Corporation