



20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@0 -35.62 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:46:14


20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@0 -47.45 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:45:30


20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@50 -46.74 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:46:03


20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@50 -35.72 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:46:26


20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB50@0 -47.34 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:49:56


20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB50@0 -35.73 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 21:50:16

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -46.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:07:42

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -35.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:08:18

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -35.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:26:05

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -47.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:09:14

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -41.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:10:13

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -35.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:10:45

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:11:38

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:11:55

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@159 -35.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:13:05

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@159 -47.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:12:48

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB160@0 -46.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:13:58

30MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB160@0 -35.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:14:54

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@0 -35.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:16:04

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@0 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:15:46

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@159 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:16:57

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@159 -35.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:17:30

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB160@0 -47.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:18:22

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB160@0 -35.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:18:40

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -35.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:19:51

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -47.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:19:32

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@215 -46.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:20:43

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@215 -35.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:21:15

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -35.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:22:24

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -39.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:22:07

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -36.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:31:59

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:31:41

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@215 -47.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:33:03

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@215 -35.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:33:35

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB216@0 -35.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:35:04

40MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB216@0 -47.48 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:34:46


40MHz_15kHz_3960MHz_DFT-s-OFDM QPSK_RB1@0 -35.63 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:37:05


40MHz_15kHz_3960MHz_DFT-s-OFDM QPSK_RB1@0 -46.63 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:36:45


40MHz_15kHz_3960MHz_DFT-s-OFDM QPSK_RB1@215 -35.82 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:42:46


40MHz_15kHz_3960MHz_DFT-s-OFDM QPSK_RB1@215 -46.91 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:42:29


40MHz_15kHz_3960MHz_DFT-s-OFDM QPSK_RB216@0 -35.12 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:44:36


40MHz_15kHz_3960MHz_DFT-s-OFDM QPSK_RB216@0 -46.24 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:44:16


40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -47.43 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:51:40


40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -35.38 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:52:02


40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -36.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:54:42


40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -47.17 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:54:26


40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -47.37 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:55:54


40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -35.98 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 21:56:40

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -36.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:58:16

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:57:46

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@105 -35.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:02:05

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@105 -47.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:59:28

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB100@0 -35.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:03:12

40MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB100@0 -46.82 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:02:55


40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@0 -35.69 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:04:19


40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@0 -46.81 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:04:03


40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@105 -46.54 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:07:33


40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@105 -35.71 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:08:05


40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB100@0 -46.09 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:08:56


40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB100@0 -35.45 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:09:53


50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -46.95 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:45:27


50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -35.78 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:45:45


50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -34.80 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:47:01


50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -47.22 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:46:37


50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -41.21 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:47:53


50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -35.26 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:48:11


50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.92 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:49:39


50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.70 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:49:57


50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@269 -35.79 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:51:35


50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@269 -46.98 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:51:17


50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -46.86 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:52:28


50MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -35.46 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:52:45


50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0 -35.60 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:54:21


50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0 -37.91 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:54:03


50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@269 -47.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:55:50


50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@269 -35.45 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:56:07


50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB270@0 -35.72 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 20:57:56


50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB270@0 -46.82 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 20:57:39

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -35.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:12:23

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -47.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:12:06

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:13:13

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -35.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:13:58

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -46.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:15:15

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -35.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:15:58

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -34.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:19:17

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:18:19

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@132 -46.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:44:00

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@132 -35.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:44:21

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB128@0 -35.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:45:39

50MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB128@0 -46.90 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:45:12


50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0 -36.06 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:48:17


50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@0 -47.30 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:48:00


50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@132 -47.35 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:49:11


50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@132 -35.62 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:49:29


50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB128@0 -35.19 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 22:51:05


50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB128@0 -47.13 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 22:50:20

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -35.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:52:16

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -46.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:51:58

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -46.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:53:08

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -35.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:53:24

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -35.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:54:34

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -46.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 22:54:16

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:08:58

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:09:30

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@161 -47.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:11:42

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@161 -35.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:12:22

60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB162@0 -47.17 dBm









ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:13:53


60MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB162@0 -35.45 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:14:19




70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -46.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:23:14

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -35.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:24:06

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -46.14 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:25:15

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -49.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:25:21

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -43.78 dBm









ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:26:10


70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -36.02 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:27:03




70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@0 -35.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:56:59

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@0 -45.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:56:42

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@188 -35.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:58:07

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@188 -47.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:57:51

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB180@0 -40.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:59:00

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB180@0 -35.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 23:59:31

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -46.99 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:00:43

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -35.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:01:00

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@216 -35.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:02:24

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@216 -47.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:02:07

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -35.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:03:34

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -46.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:03:17

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:26:52

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -36.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:27:32

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@216 -35.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:31:53

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@216 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:31:04

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB216@0 -47.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:32:44

80MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB216@0 -35.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:33:00

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@0 -35.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:11:25

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@0 -45.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:10:55

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@216 -35.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:12:58

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@216 -47.06 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:12:37

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB216@0 -47.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:13:50

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB216@0 -35.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:14:22

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0 -47.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:45:01

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0 -35.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:45:59

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@244 -47.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:54:58

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@244 -36.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:55:15

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB243@0 -35.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:50:03

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB243@0 -47.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:49:46

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:33:51

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:34:09

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@244 -36.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:35:17

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@244 -46.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:35:00

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB243@0 -37.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:36:07

90MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB243@0 -35.11 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:37:05


90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@0 -46.85 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:15:15


90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@0 -35.62 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:15:56


90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@244 -35.47 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:17:04


90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@244 -45.01 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:16:47


90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB243@0 -47.37 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:17:56


90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB243@0 -35.84 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 23.MAY.2024 00:18:29

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:51:15

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -35.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:51:32

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@272 -35.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:52:39

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@272 -46.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:52:22

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -47.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:53:30

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -34.56 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:53:47


100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.21 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:37:56


100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.47 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:38:54


100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@272 -47.53 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:40:00


100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@272 -35.20 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:40:58


100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -47.37 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 23.MAY.2024 00:41:49


100MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB270@0 -34.97 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 23.MAY.2024 00:42:47

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@0 -35.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:20:22

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@0 -45.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:19:22

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@272 -35.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:21:30

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@272 -46.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:21:14

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB270@0 -47.11 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:22:23


100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB270@0 -34.78 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 23.MAY.2024 00:22:40


n78_1

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -46.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:47:30

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -37.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:48:25

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@23 -47.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:49:20

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@23 -37.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:50:15

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0 -38.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:52:05

10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0 -47.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:51:10

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:52:58

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:53:53

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23 -46.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:54:48

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23 -38.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:55:43

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0 -47.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:56:38

10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0 -37.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:57:33

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0 -47.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:58:27

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0 -37.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:59:22

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23 -37.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:01:11

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23 -46.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:00:16

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0 -47.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:02:05

10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0 -37.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:03:00

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:03:53

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -38.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:04:48

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:06:38

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@37 -45.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:05:43

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB36@0 -38.31 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:08:28

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.88 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 04:07:32