



A.6.2 Measurement Plots



Note: All results have been included cable loss.











Note: All results have been included cable loss.

802.11n-HT20

AUX


Main










Note: All results have been included cable loss.

802.11n-HT40

AUX



Main











Note: All results have been included cable loss.

802.11ax-HE20


AUX

Main



Note: All results have been included cable loss.

802.11ax-HE40



Note: All results have been included cable loss.


Audix Technology Corp.

No. 491, Zhongfu Rd., Linkou Dist.,


New Taipei City 244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303




Note: All results have been included cable loss.




Note: All results have been included cable loss.



Note: All results have been included cable loss.



Note: All results have been included cable loss.



Note: All results have been included cable loss.