


FCC Part 24E


B2 , Normal

1.4MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Teeter:Loge Long  
Date: 2.APR.2025 21:34:16

1.4MHz\_Low\_QPSK\_6@0




ProjectNo.:2502R38805E-RF Teeter:Loge Long  
Date: 2.APR.2025 21:34:43

1.4MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Teeter:Loge Long  
Date: 2.APR.2025 21:35:11

1.4MHz\_Low\_16QAM\_6@0




ProjectNo.:2502R38805E-RF Teeter:Loge Long  
Date: 2.APR.2025 21:35:37

1.4MHz\_High\_QPSK\_1@5




ProjectNo.:2502R38805E-RF Teeter:Loge Long  
Date: 2.APR.2025 21:36:05

1.4MHz\_High\_QPSK\_6@0




ProjectNo.:2502R38805E-RF Teeter:Loge Long  
Date: 2.APR.2025 21:36:31

1.4MHz\_High\_16QAM\_1@5




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:36:58

1.4MHz\_High\_16QAM\_6@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:37:27

3MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:40:34

3MHz\_Low\_QPSK\_15@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:41:07

3MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:41:41

3MHz\_Low\_16QAM\_15@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:42:14

3MHz\_High\_QPSK\_1@14




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:42:18

3MHz\_High\_QPSK\_15@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:43:21

3MHz\_High\_16QAM\_1@14




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:43:55

3MHz\_High\_16QAM\_15@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:44:29

5MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:46:22

5MHz\_Low\_QPSK\_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:46:54

5MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:47:26

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:47:56

5MHz\_High\_QPSK\_1@24




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:48:27

5MHz\_High\_QPSK\_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:48:57

5MHz\_High\_16QAM\_1@24




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:49:26

5MHz\_High\_16QAM\_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:49:56

10MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:51:52

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:52:33

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:53:14

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:53:55

10MHz\_High\_QPSK\_1@49




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:54:37

10MHz\_High\_QPSK\_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:55:18

10MHz\_High\_16QAM\_1@49




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:56:01

10MHz\_High\_16QAM\_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:56:44

15MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:58:59

15MHz\_Low\_QPSK\_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 21:59:52

15MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:00:44

15MHz\_Low\_16QAM\_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:01:35

15MHz\_High\_QPSK\_1@74




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:02:27

15MHz\_High\_QPSK\_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:03:18

15MHz\_High\_16QAM\_1@74




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:04:09

15MHz\_High\_16QAM\_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:05:01

20MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:07:16

20MHz\_Low\_QPSK\_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:08:20

20MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:09:23

20MHz\_Low\_16QAM\_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:10:26

20MHz\_High\_QPSK\_1@99




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:11:28

20MHz\_High\_QPSK\_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:12:29

20MHz\_High\_16QAM\_1@99



ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:13:31

20MHz\_High\_16QAM\_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:14:32


FCC Part 27

B4 , Normal


1.4MHz\_Low\_QPSK\_1@0




1.4MHz\_Low\_QPSK\_6@0




1.4MHz\_Low\_16QAM\_1@0




1.4MHz\_Low\_16QAM\_6@0




1.4MHz\_High\_QPSK\_1@5



1.4MHz\_High\_QPSK\_6@0




1.4MHz\_High\_16QAM\_1@5




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:19:22

1.4MHz\_High\_16QAM\_6@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:19:54

3MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:21:52

3MHz\_Low\_QPSK\_15@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:22:27

3MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:23:03

3MHz\_Low\_16QAM\_15@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:23:38

3MHz\_High\_QPSK\_1@14




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:24:14

3MHz\_High\_QPSK\_15@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:24:49

3MHz\_High\_16QAM\_1@14




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:25:25

3MHz\_High\_16QAM\_15@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:26:01

5MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:27:56

5MHz\_Low\_QPSK\_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:28:29

5MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:29:03

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:29:36

5MHz\_High\_QPSK\_1@24




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:30:09

5MHz\_High\_QPSK\_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:30:42

5MHz\_High\_16QAM\_1@24




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:31:15

5MHz\_High\_16QAM\_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:31:48

10MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:34:00

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:34:43

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:35:25

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:36:08

10MHz\_High\_QPSK\_1@49




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:36:51

10MHz\_High\_QPSK\_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:37:33

10MHz\_High\_16QAM\_1@49




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:38:18

10MHz\_High\_16QAM\_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:39:04

15MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:41:23

15MHz\_Low\_QPSK\_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:42:18

15MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:43:13

15MHz\_Low\_16QAM\_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:44:07

15MHz\_High\_QPSK\_1@74




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:45:02

15MHz\_High\_QPSK\_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:45:56

15MHz\_High\_16QAM\_1@74




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:46:51

15MHz\_High\_16QAM\_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:47:44

20MHz\_Low\_QPSK\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:50:17

20MHz\_Low\_QPSK\_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:51:23

20MHz\_Low\_16QAM\_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:52:30

20MHz\_Low\_16QAM\_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:53:36

20MHz\_High\_QPSK\_1@99




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:54:42

20MHz\_High\_QPSK\_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:55:48

20MHz\_High\_16QAM\_1@99



ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:56:55


20MHz\_High\_16QAM\_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long  
Date: 2.APR.2025 22:58:00

B7 , Normal


5MHz\_Low\_QPSK\_1@0




5MHz\_Low\_QPSK\_25@0




5MHz\_Low\_16QAM\_1@0



5MHz\_Low\_16QAM\_25@0



5MHz\_High\_QPSK\_1@24



5MHz\_High\_QPSK\_25@0

