




FCC ID:NEODSBR4008PSA
FCC ID:NEODSBR4008CLA

To whom it may concern

Attestation exhibit

According to KDB 935210 D02 4 Industrial (Part 90, Part 20) Signal Booster Specifics, Cobham Inc., as manufacturer, declare that the warning label below:

Part 90 Signal boosters		THIS IS A 90.219 CLASS A DEVICE	
	WARNING!!! This is NOT a CONSUMER device. This device is designed for installation by FCC LICENCEES and QUALIFIED INSTALLERS. You must have an FCC LICENCE or express consent of an FCC Licensee to operate this device. (You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration .)		
Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.			
This repeater must be operated as a Part 90 Class A repeater. The installation procedure must result in the signal booster complying with FCC requirements 90.219(d). In order to meet FCC requirements 90.219(d) , it may be necessary for the installer to reduce the UL and/or DL output power for certain installations.			

Will appear:
On the Product
On the Packaging
In the Product manual
In the Product data sheet
In the Product sales Brochure &
All customer accessible electronic media.