## LEEDARSON LIGHTING CO., LTD.

ADD: Xingda Road, Xingtai Industrial Zone, Changtai County, Zhangzhou, Fujian,

China

TEL: (86) 592-3699897 FAX: (86) 592-3699627

Mail Address: cert@leedarson.com

Date: 2022-10-20

## **Attestation Letter**

FEDERAL COMMUNICATIONS COMMISSION

Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Dear Sir or Madam:

The chip ESP32-U4WD installed in our product: LED Lamp (model name: 12A19060WRGBWH1, 12aSy-A800ST-Q1T-xx (Where "y" may be "A" to "Z", which designates for different enclosure pattern design; "xx" may be "00" to "99", which designates for different beam angle, color of eyelet contact, different package of style and CCT.), 12A19060WRGBWHz, ("z" may be "1" to "9", which designates for different beam angle, color of eyelet contact, different package of style and CCT.), FCC ID: 2AB2Q-12A800STQT), that only BLE 1M and WIFI(802.11b/g/n ht20, 802.11n ht40) were activated; the other functions are disabled by using software.

Please contact me if there is need for any additional clarification or information.

Best Regards, Sincerely Yours,

Signature:

Typed or Printed Name: Vick Zhang

Gick Zhang

Title: safety engineer