FCC TEST REPORT Report No.: F310809

1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

FCC ID : JCKGN-AP101B

Page No. : 1 of 3 Issued Date : May 10, 2003 FCC TEST REPORT Report No.: F310809



SIDE VIEW

SPORTON International Inc. FCC ID : JCKGN-AP101B

TEL: 886-2-2696-2468 Page No. : 2 of 3
FAX: 886-2-2696-2255 Issued Date : May 10, 2003


FCC TEST REPORT Report No.: F310809

1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

FCC ID : JCKGN-AP101B

Page No. : 3 of 3 Issued Date : May 10, 2003