


Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19

IC: 2978A-BC100T19

Internal Photos







Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19

IC: 2978A-BC100T19







Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19

IC: 2978A-BC100T19






Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19


IC: 2978A-BC100T19




Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19

IC: 2978A-BC100T19






Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19


IC: 2978A-BC100T19





IC: 2978A-BC100T19







Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19

IC: 2978A-BC100T19







Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19

IC: 2978A-BC100T19





Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M21906-19106-C-1

FCC ID: M5X-BC100T19

IC: 2978A-BC100T19

