

ORAIMO TECHNOLOGY LIMITED

ADD: Flat 39, 8/F., Block D, Wah Lok Industrial Centre, 31-35 Shan Mei Street, Fotan, NT  
Hong Kong

Tel: 0755 61803856

Fax Number: 86-755-33979211

Email: dollyphin@oraimo.com

Date: 2021-10-26

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division


7435 Oakland Mills Road

Columbia, MD 21046

Dear Sir/Madam,

The RF chip, model BT8896A, which installed in our product True Wireless Stereo Earbuds, Model: OEB-E02D, FCC ID: 2AXYP-OEB-E02D-R, supports BDR (GFSK), EDR ( $\pi/4$ -DQPSK, 8DPSK), BLE 1M and BLE 2M functions. For use in America and this chip will not support/enable BLE 1M and BLE 2M. The BLE 1M and BLE 2M has been shielded by the manufacturer using the software

Signature:



Greeny Xian

Title: Manager