FCC WARNING	However, there is no guarantee that interference will not occur in a	such modifications could void the user's authority to operate the
This device complies with part 15 of the FCC Rules. Operation is	particular installation. If this equipment does cause harmful	equipment. The device has been evaluated to meet general RF
subject to the following two conditions: (1) This device may not cause	interference to radio or television reception, which can be	exposure requirement. This equipment complies with FCC's RF
harmful interference, and (2) this device must accept any interference	determined by turning the equipment off and on, the user is	radiation exposure limits set forth for an uncontrolled
received, including interference that may cause undesired operation.	encouraged to try to correct the interference by one or more of the	environment. This device and its antenna(s) must not be co-located
Note: This equipment has been tested and found to comply with the	following measures:	or conjunction with any other antenna or transmitter.
limits for a Class B digital device, pursuant to part 15 of the FCC Rules.	—Reorient or relocate the receiving antenna.	FCC ID:2BK68-Q62
These limits are designed to provide reasonable protection against	-Increase the separation between the equipment and receiver.	
harmful interference in a residential installation. This equipment	Connect the equipment into an outlet on a circuit different from	
generates, uses and can radiate radio frequency energy and, if not	that to which the receiver is connected.	
installed and used in accordance with the instructions, may cause	—Consult the dealer or an experienced radio/TV technician for help.	
harmful interference to radio communications.	Note: The Grantee is not responsible for any changes or modifications	
	not expressly approved by the party responsible for compliance.	