



Band-5_10-MHz_High_QPSK_RB50#0




Date: 19.DEC.2023 22:50:49

Band-5_10-MHz_High_16QAM_RB50#0




Date: 19.DEC.2023 22:51:12

Band-7_5-MHz_Low_QPSK_RB25#0




Date: 19.DEC.2023 20:56:19

Band-7_5-MHz_Low_16QAM_RB25#0




Date: 19.DEC.2023 20:56:38

Band-7_5-MHz_Middle_QPSK_RB25#0




Date: 19.DEC.2023 20:56:59

Band-7_5-MHz_Middle_16QAM_RB25#0




Date: 19.DEC.2023 20:57:19

Band-7_5-MHz_High_QPSK_RB25#0




Date: 19.DEC.2023 20:57:37

Band-7_5-MHz_High_16QAM_RB25#0




Date: 19.DEC.2023 20:58:03

Band-7_10-MHz_Low_QPSK_RB50#0




Date: 19.DEC.2023 20:58:40

Band-7_10-MHz_Low_16QAM_RB50#0




Date: 19.DEC.2023 20:59:12

Band-7_10-MHz_Middle_QPSK_RB50#0




Date: 19.DEC.2023 20:59:42

Band-7_10-MHz_Middle_16QAM_RB50#0




Date: 19.DEC.2023 21:00:15

Band-7_10-MHz_High_QPSK_RB50#0




Date: 19.DEC.2023 21:00:36

Band-7_10-MHz_High_16QAM_RB50#0




Date: 19.DEC.2023 21:01:02

Band-7_15-MHz_Low_QPSK_RB75#0




Date: 19.DEC.2023 21:01:33

Band-7_15-MHz_Low_16QAM_RB75#0




Date: 19.DEC.2023 21:01:56

Band-7_15-MHz_Middle_QPSK_RB75#0




Date: 19.DEC.2023 21:02:29

Band-7_15-MHz_Middle_16QAM_RB75#0




Date: 19.DEC.2023 21:02:49

Band-7_15-MHz_High_QPSK_RB75#0




Date: 19.DEC.2023 21:03:10

Band-7_15-MHz_High_16QAM_RB75#0




Date: 19.DEC.2023 21:03:30

Band-7_20-MHz_Low_QPSK_RB100#0




Date: 19.DEC.2023 21:04:04

Band-7_20-MHz_Low_16QAM_RB100#0




Date: 19.DEC.2023 21:04:30

Band-7_20-MHz_Middle_QPSK_RB100#0




Date: 19.DEC.2023 21:04:54

Band-7_20-MHz_Middle_16QAM_RB100#0




Date: 19.DEC.2023 21:05:33

Band-7_20-MHz_High_QPSK_RB100#0




Date: 19.DEC.2023 21:06:01

Band-7_20-MHz_High_16QAM_RB100#0




Date: 19.DEC.2023 21:06:24

Band-38_5-MHz_Low_QPSK_RB25#0




Date: 22.DEC.2023 19:59:18

Band-38_5-MHz_Low_16QAM_RB25#0




Date: 22.DEC.2023 19:59:35

Band-38_5-MHz_Middle_QPSK_RB25#0




Date: 22.DEC.2023 20:00:02

Band-38_5-MHz_Middle_16QAM_RB25#0




Date: 22.DEC.2023 20:00:23

Band-38_5-MHz_High_QPSK_RB25#0




Date: 22.DEC.2023 20:00:44

Band-38_5-MHz_High_16QAM_RB25#0




Date: 22.DEC.2023 20:01:01

Band-38_10-MHz_Low_QPSK_RB50#0




Date: 22.DEC.2023 20:01:27

Band-38_10-MHz_Low_16QAM_RB50#0




Date: 22.DEC.2023 20:01:50

Band-38_10-MHz_Middle_QPSK_RB50#0




Date: 22.DEC.2023 20:02:11

Band-38_10-MHz_Middle_16QAM_RB50#0




Date: 22.DEC.2023 20:02:37

Band-38_10-MHz_High_QPSK_RB50#0




Date: 22.DEC.2023 20:03:04

Band-38_10-MHz_High_16QAM_RB50#0




Date: 22.DEC.2023 20:03:37

Band-38_15-MHz_Low_QPSK_RB75#0




Date: 22.DEC.2023 20:04:03

Band-38_15-MHz_Low_16QAM_RB75#0




Date: 22.DEC.2023 20:04:26

Band-38_15-MHz_Middle_QPSK_RB75#0




Date: 22.DEC.2023 20:04:53

Band-38_15-MHz_Middle_16QAM_RB75#0




Date: 22.DEC.2023 20:05:23

Band-38_15-MHz_High_QPSK_RB75#0




Date: 22.DEC.2023 20:05:53

Band-38_15-MHz_High_16QAM_RB75#0




Date: 22.DEC.2023 20:06:16

Band-38_20-MHz_Low_QPSK_RB100#0




Date: 22.DEC.2023 20:06:45

Band-38_20-MHz_Low_16QAM_RB100#0




Date: 22.DEC.2023 20:07:08

Band-38_20-MHz_Middle_QPSK_RB100#0




Date: 22.DEC.2023 20:07:32

Band-38_20-MHz_Middle_16QAM_RB100#0




Date: 22.DEC.2023 20:07:59

Band-38_20-MHz_High_QPSK_RB100#0




Date: 22.DEC.2023 20:08:29

Band-38_20-MHz_High_16QAM_RB100#0




Date: 22.DEC.2023 20:08:52

Band-41_5-MHz_Low_QPSK_RB25#0




Date: 19.DEC.2023 23:15:28

Band-41_5-MHz_Low_16QAM_RB25#0




Date: 19.DEC.2023 23:15:45

Band-41_5-MHz_Middle_QPSK_RB25#0




Date: 19.DEC.2023 23:16:06

Band-41_5-MHz_Middle_16QAM_RB25#0




Date: 19.DEC.2023 23:16:29

Band-41_5-MHz_High_QPSK_RB25#0




Date: 19.DEC.2023 23:16:46

Band-41_5-MHz_High_16QAM_RB25#0




Date: 19.DEC.2023 23:17:03

Band-41_10-MHz_Low_QPSK_RB50#0




Date: 19.DEC.2023 23:16:07

Band-41_10-MHz_Low_16QAM_RB50#0




Date: 19.DEC.2023 23:16:27

Band-41_10-MHz_Middle_QPSK_RB50#0




Date: 19.DEC.2023 23:16:54

Band-41_10-MHz_Middle_16QAM_RB50#0




Date: 19.DEC.2023 23:19:23

Band-41_10-MHz_High_QPSK_RB50#0




Date: 19.DEC.2023 23:19:47

Band-41_10-MHz_High_16QAM_RB50#0




Date: 19.DEC.2023 23:20:13

Band-41_15-MHz_Low_QPSK_RB75#0




Date: 19.DEC.2023 23:21:15

Band-41_15-MHz_Low_16QAM_RB75#0




Date: 19.DEC.2023 23:21:35

Band-41_15-MHz_Middle_QPSK_RB75#0




Date: 19.DEC.2023 23:21:56

Band-41_15-MHz_Middle_16QAM_RB75#0




Date: 19.DEC.2023 23:22:19

Band-41_15-MHz_High_QPSK_RB75#0




Date: 19.DEC.2023 23:22:43

Band-41_15-MHz_High_16QAM_RB75#0




Date: 19.DEC.2023 23:23:15

Band-41_20-MHz_Low_QPSK_RB100#0




Date: 19.DEC.2023 23:24:31

Band-41_20-MHz_Low_16QAM_RB100#0




Date: 19.DEC.2023 23:25:07

Band-41_20-MHz_Middle_QPSK_RB100#0




Date: 19.DEC.2023 23:25:34

Band-41_20-MHz_Middle_16QAM_RB100#0




Date: 19.DEC.2023 23:25:54

Band-41_20-MHz_High_QPSK_RB100#0



Date: 19.DEC.2023 23:26:27

Band-41_20-MHz_High_16QAM_RB100#0



Date: 19.DEC.2023 23:26:56