


Tracker(2QBP100) / Dongle(2QCD100)

setup guide

About the Tracker

Tracker(2QBP100) is a self-tracking device. Attach it to a real object or human body, and put yourself in the virtual reality applications.

1. Tracker (2QBP100)
2. Power button
3. Status light
4. POGO pin
5. USB Type-C port
6. Dongle (2QCD100)
7. Dongle cradle
8. Camera



Charging Tracker

Charging **Tracker** using the USB Type-C cable that came in the box.

Connect one end of the USB Type-C cable to **Tracker** and the other end to your computer.

When **Tracker** is fully charged, status light will go back to the previous status.

You can also use a power adapter with the USB Type-C cable to charge **Tracker**.

Turning Tracker on or off

To turn **Tracker** on, brief press the POWER button. The status light will turn blue.

To turn **Tracker** off, press the POWER button for 5 seconds.

Using the dongle and pairing Tracker

The dongle needs to be connected to the headset for **Tracker** to be tracked.

Connect the dongle to your headset

1. Connect the dongle to headset USB-C port.
2. From your VR headset, turn on Wi-Fi, then go to **Settings > inputs > Motion Trackers**, pair new device.
3. Press the **Tracker** POWER button for 2 seconds. The status light will blink blue.
4. Wait for the status light to turn **green** or **blink red/green**. This means pairing is successful.

Status light

Charging	Solid amber
Fully charged	Back to the previous status
Pairing mode	Blinking blue
Battery low	Blinking red
Connected	Solid green



© 2023 HTC Corporation.

All Rights Reserved.

HTC and the HTC logo are trademarks of HTC Corporation (or HTC).