

LABEL

The label shown below is affixed on the bottom of the Access Point unit.
The label material is PVC with a permanent adhesive.

Label location on the AP bottom, FCC ID:OJFMA850A1





Ofek One Center Building B, LOD 71293, ISRAEL

This device complies with Part of the FCC Rules.

Operation is subject to the following two conditions:

- 1) This device may not cause harmful interference ,and
- 2) This device must accept any interference received ,
including interference that may cause undesired operation.

Catalog Model : 850A

FCC ID : OJFMA850A1

Manufactured : **Month - Year**

For Cisco 1242 AP