



Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:12:02

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:12:24


Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)



Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.MAR.2022 13:18:44

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:14:15

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.MAR.2022 13:20:08

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:15:11

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:15:43

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:16:08

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:16:43

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:17:06

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.MAR.2022 13:21:49

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:17:56

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:18:28

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:18:56

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:19:25

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:19:47


Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)



Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:21:29

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:21:48

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:22:19

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:22:45

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:23:22

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:23:47


Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)



Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.MAR.2022 13:23:03

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:25:32

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:26:05

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:26:24

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:26:58

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:27:20

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:27:48

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 10:28:07

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:51:34

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:52:00

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:52:32

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:52:54

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:53:32

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:53:57

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:54:33

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:54:55

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:55:29

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:55:48

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:56:22

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:56:51

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:57:31

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:57:56

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:58:29

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:58:51

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 11:59:32

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 11:59:58

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 12:00:38

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 12:01:00

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 12:01:39

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 12:02:01

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 12:02:39

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 12:03:01

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:26:45

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:27:04

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:27:29

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:27:58

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:28:26

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:28:52

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:29:31

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:29:53

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:30:24

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:30:46

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:31:20

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:31:42

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:32:20

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:32:48

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:33:27

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:33:52

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:34:27

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:34:50

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:35:33

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:36:02


Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)



Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 13:37:53

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 13:38:18

Band 66_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:43:05

Band 66_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:43:27

Band 66_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:43:56

Band 66_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:44:25

Band 66_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:45:03

Band 66_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:45:28

Band 66_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:46:00

Band 66_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:46:25

Band 66_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:46:57

Band 66_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:47:26

Band 66_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:47:54

Band 66_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:48:13

Band 66_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:48:47

Band 66_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:49:16

Band 66_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:49:41

Band 66_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:50:03

Band 66_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:50:38

Band 66_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:51:07

Band 66_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:51:41

Band 66_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:52:06

Band 66_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:52:37

Band 66_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:53:06

Band 66_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:53:37

Band 66_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:53:56

Band 66_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:54:34

Band 66_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:55:03

Band 66_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:55:38

Band 66_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:56:00

Band 66_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:56:39

Band 66_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:57:10

Band 66_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:57:54

Band 66_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:58:22

Band 66_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 16:59:04

Band 66_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 29.MAR.2022 16:59:32

Band 66_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 29.MAR.2022 17:00:11

Band 66_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)



Date: 29.MAR.2022 17:00:39