

# SONY

Sony Corporation

1-7-1 Konan, Minato-ku Tokyo 108-0075 Japan

## Request for Class II Permissive Change

March 3, 2023

UL Verification Services Inc.  
47173 Benicia Street, Fremont, CA 94538

FCC ID : AK8RCS300  
Applicant : Sony Group Corporation

To Whom It May Concern:

This is to request a Class II permissive change for FCC ID: AK8RCS300 granted on 09/22/2021.  
We changed the following points from the original model.

- RF parameter settings for RFFE.
- The ratings of the components in Filter and Matching circuit

Please refer to attached "Theory of Operation" and "Schematics" for details of these modifications.

Meanwhile we submit the following documents related to this change. There is no change before and after change except for these documents.

<input checked="" type="checkbox"/>	Test Report
<input checked="" type="checkbox"/>	RF Exposure
<input type="checkbox"/>	External Photo
<input checked="" type="checkbox"/>	Internal Photo
<input type="checkbox"/>	User Manual
<input type="checkbox"/>	Label Drawing/ Location
<input type="checkbox"/>	Block Diagram
<input checked="" type="checkbox"/>	Specification
<input checked="" type="checkbox"/>	Schematic Diagram
<input type="checkbox"/>	Parts List

This time, we performed the testing and confirmed that this product still meets the minimum requirements of the applicable rules of FCC. Please refer to the test report submitted with this application.

Thank you for your attention to this matter.

Sincerely,



Atsushi Mukoyama  
Senior Manager  
Section 3, Department 4  
Quality Assurance & Service Operation Division  
Sony Corporation