

Thundercomm Technology Co., Ltd
Address: Building 4, No.99, Data Valley Middle Road, Xiantao District, Yubei District,
Chongqing, China
Tel: +86 010-82036511
Fax: +86 010-82036511
E-mail: Zhouqy0710@thundersoft.com

Date: 2021-04-09

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

Subject: FCC Class II Permission change for FCC ID: 2AOHHTURBOXSOMD845
Original Grant Date: 2019-01-24

Dear Sir/Madam,

This is to request a Class II permission change to our product name: Thundersoft TurboX D845 SOM; Model: TurboX-D845-SOM; (FCC ID: 2AOHHTURBOXSOMD845), the device is identical to the previously certified except for the changes as below for details;


- 1) Add a kind of Antenna
- 2) Changing the company address to "Building 4, No.99, Data Valley Middle Road Xiantao District, Yubei District, Chongqing, China"

This authorization is valid until further written notice from the applicant.

Please contact me if you have any questions or need future information regarding this application.

Sincerely Yours,

Signature:



Qiyong Zhou

Manager