

YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD.  
No.666 Hu'an Rd. Huli District Xiamen City, Fujian, P.R. China  
Tel: 86-592-5702000  
Fax: 86-592-5702455  
Email: chenjl@yealink.com

## FCC certification No. Cover Letter


We, YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD., hereby submit justification for placing the FCC certification No. in the associated user's manual.

According to the FCC regulation, the FCC certification No. should be printed on the Bluetooth Headset, but as the Bluetooth Headset are too small to print the label (FCC ID: T2C-BHM711) , it will be moved to the user manual. The details are as below:

- A. Side surface (A): The side surface does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.




- B. Top cover (B): The top cover does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.



Conclusion: Based on the above description of area A to B, we conclude that the device is unquestionably too small for enabling the FCC certification No. to be printed onto any surface. We therefore request to move the FCC certification No. to the user's manual.

Label:



Stick the label on last page of user manual

Best regards,  
Signature:

Stone Lu  
Vice General Manager