



Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT3:

QPSK










Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT4:

QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

20MHz @3560.01MHz ANT1

QPSK









Report No.: AAEMT/RF/241224-01-01

64QAM









Report No.: AAEMT/RF/241224-01-01

ANT2

QPSK










Report No.: AAEMT/RF/241224-01-01









Report No.: AAEMT/RF/241224-01-01

ANT3

QPSK










Report No.: AAEMT/RF/241224-01-01









Report No.: AAEMT/RF/241224-01-01

ANT4

QPSK









Report No.: AAEMT/RF/241224-01-01









Report No.: AAEMT/RF/241224-01-01 20MHz @3625.005MHz ANT1 QPSK









Report No.: AAEMT/RF/241224-01-01

64QAM









Report No.: AAEMT/RF/241224-01-01

ANT2 QPSK









Report No.: AAEMT/RF/241224-01-01

64QAM









Report No.: AAEMT/RF/241224-01-01

ANT3 QPSK










Report No.: AAEMT/RF/241224-01-01

64QAM









Report No.: AAEMT/RF/241224-01-01

ANT4

QPSK









Report No.: AAEMT/RF/241224-01-01

64QAM










Report No.: AAEMT/RF/241224-01-01

20MHz @3690MHz ANT1 QPSK










Report No.: AAEMT/RF/241224-01-01

64 QAM









Report No.: AAEMT/RF/241224-01-01 **ANT2** OPSK









Report No.: AAEMT/RF/241224-01-01









Report No.: AAEMT/RF/241224-01-01

ANT3

QPSK









Report No.: AAEMT/RF/241224-01-01









Report No.: AAEMT/RF/241224-01-01

ANT4

QPSK









Report No.: AAEMT/RF/241224-01-01









Report No.: AAEMT/RF/241224-01-01

40MHz @3570.24MHz ANT1 QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT2

QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT3

QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT4

QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01 40MHz @3625.005MHz

ANT1

QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT2

QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT3 QPSK










Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT4

QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

40MHz @**3679.755MHz ANT1**QPSK









Report No.: AAEMT/RF/241224-01-01

64QAM










Report No.: AAEMT/RF/241224-01-01

ANT2

QPSK









Report No.: AAEMT/RF/241224-01-01 64QAM









Report No.: AAEMT/RF/241224-01-01

ANT3

QPSK



