

**TO: FCC**  
**ATTN: Mr. Joe Dichoso**  
**FROM: Len Sabato/ Horizon**  
**Subject: BRWXF421EX Manual Addition**  
**Reference # 12093 EA96000**

**RE) Manual Addition to comply with Section 95.653**

**We will be adding the following information to page 28 of the instruction manual:**

**“ The Federal Communications Commission (FCC) requires that changes in radio frequency must be performed by an authorized service technician only (Horizon Service Center).**

**Any frequency changes made by a non-certified technician may result in a violation of the FCC rules”.**

**We are hopeful that this warning will be acceptable. If you require any changes in the wording of this addition, please advise.**

**Best Regards;**

**Len Sabato**