



Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 4.DEC.2023 09:49:59

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 4.DEC.2023 09:50:16

Band 5_10 MHz_High_QPSK_RB50#0




Date: 4.DEC.2023 09:50:33

Band 5_10 MHz_High_16QAM_RB50#0




Date: 4.DEC.2023 09:50:52

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 4.DEC.2023 09:51:23

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 4.DEC.2023 09:51:43

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 4.DEC.2023 09:52:00

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 4.DEC.2023 09:52:19

Band 7_5 MHz_High_QPSK_RB25#0




Date: 4.DEC.2023 09:52:45

Band 7_5 MHz_High_16QAM_RB25#0




Date: 4.DEC.2023 09:53:08

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 4.DEC.2023 09:55:20

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 4.DEC.2023 09:55:38

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 4.DEC.2023 09:55:55

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 4.DEC.2023 09:56:11

Band 7_10 MHz_High_QPSK_RB50#0




Date: 4.DEC.2023 09:56:25

Band 7_10 MHz_High_16QAM_RB50#0




Date: 4.DEC.2023 09:56:38

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 4.DEC.2023 10:00:44

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 4.DEC.2023 10:01:07

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 4.DEC.2023 10:01:29

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 4.DEC.2023 10:01:45

Band 7_15 MHz_High_QPSK_RB75#0




Date: 4.DEC.2023 10:02:08

Band 7_15 MHz_High_16QAM_RB75#0




Date: 4.DEC.2023 10:02:27

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 4.DEC.2023 10:03:41

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 4.DEC.2023 10:03:57

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 4.DEC.2023 10:04:14

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 4.DEC.2023 10:04:30

Band 7_20 MHz_High_QPSK_RB100#0




Date: 4.DEC.2023 10:04:47

Band 7_20 MHz_High_16QAM_RB100#0




Date: 4.DEC.2023 10:05:04

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 4.DEC.2023 10:07:27

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 4.DEC.2023 10:07:46

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 4.DEC.2023 10:08:06

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 4.DEC.2023 10:08:22

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 4.DEC.2023 10:08:39

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 4.DEC.2023 10:08:58

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 4.DEC.2023 10:15:39

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 4.DEC.2023 10:15:55

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 4.DEC.2023 10:16:12

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 4.DEC.2023 10:16:28

Band 12_3 MHz_High_QPSK_RB15#0




Date: 4.DEC.2023 10:16:42

Band 12_3 MHz_High_16QAM_RB15#0




Date: 4.DEC.2023 10:16:55

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 4.DEC.2023 10:18:59

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 4.DEC.2023 10:19:22

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 4.DEC.2023 10:19:42

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 4.DEC.2023 10:30:18

Band 12_5 MHz_High_QPSK_RB25#0




Date: 4.DEC.2023 10:30:35

Band 12_5 MHz_High_16QAM_RB25#0




Date: 4.DEC.2023 10:30:51

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 4.DEC.2023 10:32:21

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 4.DEC.2023 10:32:41

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 4.DEC.2023 10:33:04

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 4.DEC.2023 10:33:20

Band 12_10 MHz_High_QPSK_RB50#0




Date: 4.DEC.2023 10:33:40

Band 12_10 MHz_High_16QAM_RB50#0




Date: 4.DEC.2023 10:33:59

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 5.DEC.2023 15:24:02

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 5.DEC.2023 15:24:27

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 5.DEC.2023 15:24:57

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 5.DEC.2023 15:25:24

Band 41_5 MHz_High_QPSK_RB25#0




Date: 5.DEC.2023 15:25:55

Band 41_5 MHz_High_16QAM_RB25#0




Date: 5.DEC.2023 15:26:15

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 5.DEC.2023 15:26:39

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 5.DEC.2023 15:26:59

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 5.DEC.2023 15:27:17

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 5.DEC.2023 15:27:38

Band 41_10 MHz_High_QPSK_RB50#0




Date: 5.DEC.2023 15:27:56

Band 41_10 MHz_High_16QAM_RB50#0




Date: 5.DEC.2023 15:28:13

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 5.DEC.2023 15:28:58

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 5.DEC.2023 15:29:36

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 5.DEC.2023 15:30:09

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 5.DEC.2023 15:30:51

Band 41_15 MHz_High_QPSK_RB75#0




Date: 5.DEC.2023 15:31:24

Band 41_15 MHz_High_16QAM_RB75#0




Date: 5.DEC.2023 15:31:56

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 5.DEC.2023 15:32:42

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 5.DEC.2023 15:33:11

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 5.DEC.2023 15:33:38

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 5.DEC.2023 15:34:00

Band 41_20 MHz_High_QPSK_RB100#0



Date: 5.DEC.2023 15:34:23

Band 41_20 MHz_High_16QAM_RB100#0



Date: 5.DEC.2023 15:34:46