## Sentry Industries Limited UNIT 904, 9/F CHINACHEN GOLDEN PLAZA, 77 MODY ROAD, TSIM SHA TSUI EAST, KOWLOON, HONG KONG, CHINA

Aug. 1, 2024

Office of Engineering Technology Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046 USA

Subject: Explanation of differences between product types

FCC ID: 2ACP4CBTA850

Models: BTA850, BTA899, BT993, BT998, BT999, BTA900, BTA905, BTA910, BTA920, BTA930, BTA940, BTA950, BTA990,

BTA993, BTA998, BTA999, BTO300

To Whom It May Concern:

We, The Sentry Industries Limited hereby declare that the model: BTA899, BT993, BT998, BT999, BTA900, BTA905, BTA910, BTA920, BTA930, BTA940, BTA950, BTA990, BTA993, BTA998, BTA999, BTO300 is identical with the model: BTA850, except the model name.

Except for the different above, no other modification is performed.

Sincerely,

Sentry Industries Limited Signature:

2001 Melvami

[Peetu Melwani, Manager]