

FAX: (510) 661-0888


10. **SETUP PHOTOS**

RADIATED RF MEASUREMENT SETUP



ORIENTATIONS





END OF REPORT

47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 66 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.