

Declaration

We, Zhejiang OKAI Vehicle Co., Ltd. hereby states that the antenna of ES800 and EB50 is consistent with Bluetooth, and the PCB schematic diagram is consistent. The difference is that the component plug-in patch of ES800 and EB50 are different. ES800 has left and right turn signal patch plug-in, while EB50 has no turn signal plug-in, which does not affect the function of Bluetooth antenna.

Stamp:

Date: 2023.3.14

