



n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@0 -36.49dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 13:41:02

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@244 -36.97dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 13:42:04

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB243@0 -36.53dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 13:43:04

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@0 -36.27dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 13:45:23

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@272 -36.49dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 13:46:23

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB270@0 -36.33dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 13:47:24

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.12dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 13:48:25

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@272 -37.28dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 13:49:30

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB270@0 -36.88dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 13:50:30

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@0 -36.67dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 13:51:35

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@272 -36.34dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 13:52:36


n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB270@0 -35.98dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 13:53:37


n66

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.59dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 13:55:32

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@24 -38.16dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 13:56:24

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB25@0 -36.90dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 13:57:15

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.66dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 11:02:02

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@24 -38.31dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 14:02:57

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB25@0 -38.35dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 11:03:51

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.48dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 14:08:48

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@24 -37.84dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 14:09:43

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.92dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 14:10:38

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@0 -38.41dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 14:18:11

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@51 -37.77dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 14:19:06

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB50@0 -38.22dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 14:20:03

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -38.12dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 14:26:41

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@51 -38.29dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 14:27:33

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB50@0 -38.46dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 14:28:26

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 14:41:36

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB1@51 -38.46dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 14:42:25

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB50@0 -36.86dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 14:43:22

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.27dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 14:54:41

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.70dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 14:55:34

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB75@0 -37.85dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 14:56:27

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.93dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:04:59

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@78 -38.09dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:05:52

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB75@0 -37.63dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:06:46

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.74dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:11:42

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.30dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:12:39

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB75@0 -37.97dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:13:36

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB100@0 -37.91dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:18:35

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:16:40

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB1@105 -38.17dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 15:17:38

n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB100@0 -38.15dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 15:21:31

n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.96dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 15:19:37

n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@105 -38.03dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 15:20:34

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB100@0 -38.30dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 15:24:28

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB1@0 -38.41dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 15:22:34

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB1@105 -37.63dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 15:23:31

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB128@0 -37.60dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC 2024 15:30:03

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.23dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC 2024 15:28:09

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB1@132 -37.65dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC 2024 15:29:06

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB128@0 -38.07dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC 2024 15:33:00

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.70dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC 2024 15:31:06

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@132 -37.71dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC 2024 15:32:03

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB128@0 -38.11dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC.2024 15:35:17

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.03dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC.2024 15:34:02

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB1@132 -38.30dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC.2024 15:35:09

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB160@0 -37.79dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC.2024 15:43:21

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB1@0 -38.43dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC.2024 15:41:26

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB1@159 -37.90dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18 DEC.2024 15:42:23

n66_30MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB160@0 -37.84dBm




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 18.DEC.2024 15:46:15

n66_30MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.74dBm




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 18.DEC.2024 15:44:23

n66_30MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@159 -37.92dBm




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 18.DEC.2024 15:45:21

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB160@0 -38.42dBm




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 18.DEC.2024 15:53:59

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB1@0 -38.43dBm



ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 18.DEC.2024 15:52:02

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB1@159 -37.60dBm



ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 18.DEC.2024 15:53:01