

INFINIX MOBILITY LIMITED

Address: ROOM 604 6/F SOUTH TOWER WORLD FINANCE CTR HARBOUR CITY 17

CANTON ROAD TST KL, HARBOUR, Hong Kong

Tel: +86-0755-61803856; Fax: 755-33979211

Email: yiting.luo@transsion.com

Attestation Letter

Date: 2019-03-07

Dear Sir or Madam:

The RF chip, model MT6761, installed in our product: Mobile phone; Model name: X5516B (FCC ID: 2AIZN-X5516B), which supports LTE function. For use in the US market, this chip will support LTE band 2/4/5/7, not support/enable other LTE bands. The other LTE bands have been shielded by the manufacturer by using the software.

Meanwhile, the RF chip, model MT6631 which supports 5G WIFI. For use in the US market, this chip will not support/enable 5G WIFI. The 5G WIFI have been shielded by the manufacturer by using the software.

Sincerely,

Signature

Yiting Luo

Manager