



3390 East Harmony Road
Fort Collins
Colorado 80528
United States

Date: October 30, 2020

To whom it may concern,

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by HP Inc. will establish a new FCC ID: B94-RTL8852AES under HP Inc. grantee code for purpose of marketing. The original grant to REALTEK SEMICONDUCTOR CORP. will remain in effect.

Per 2.933(b)

1. The original identification is TX2-RTL8852AE.
2. The original grant date is Oct. 16, 2020.
3. The equipment is electrically identical. Only the trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

- ◆ Cover Letter
- ◆ External Photos
- ◆ FCC ID label format and location

Should there be any question, please feel free to contact us.

Sincerely yours,

Liang Rong Chiao

Liang Rong Chiao
Worldwide Technical Regulations
HP Inc.
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan
frances.liang@hp.com
T +886-2-37892469