




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


APPENDIX J: INTERNAL EUT PICTURES



PHOTOGRAPH 9: INSIDE VIEW OF THE RADIO WITHOUT THE RF PORTION




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 10: SIDE VIEW OF THE RADIO WITHOUT THE RF PORTION




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 11: RADIO RF AND LOGIC BOARDS WITH SHIELDS




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 12: RF PARTION OF THE RADIO




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 13: TOP VIEW OF THE COVER FOR THE RF PORTION




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 14: BOTTOM VIEW OF THE COVER FOR THE RF PORTION




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 15: RF AND LOGIC PART WITHOUT SHIELDS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 16: TOP VIEW OF THE LOGIC BOARD




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 17: BOTTOM VIEW OF THE LOGIC BOARD, KEYPAD



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 18: TOP VIEW OF THE BOTTOM COVER




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 19: BOTTOM VIEW OF THE TOP COVER



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 20: VIEW OF THE RF AND LOGIC BOARDS