







Band66_1.4MHz_64QAM_132665_6RB#0




Band66_3MHz_QPSK_131987_1RB#0




Band66_3MHz_QPSK_131987_1RB#14




Band66_3MHz_QPSK_131987_15RB#0







Band66_3MHz_16QAM_131987_1RB#14




Band66_3MHz_16QAM_131987_15RB#0




Band66_3MHz_16QAM_132657_1RB#0




Band66_3MHz_16QAM_132657_1RB#14




Band66_3MHz_16QAM_132657_15RB#0




Band66_3MHz_64QAM_131987_1RB#0




Band66_3MHz_64QAM_131987_1RB#14




Band66_3MHz_64QAM_131987_15RB#0




Band66_3MHz_64QAM_132657_1RB#0




Band66_3MHz_64QAM_132657_1RB#14




Band66_3MHz_64QAM_132657_15RB#0




Band66_5MHz_QPSK_131997_1RB#0




Band66_5MHz_QPSK_131997_1RB#24




Band66_5MHz_QPSK_131997_25RB#0




Band66_5MHz_QPSK_132647_1RB#0




Band66_5MHz_QPSK_132647_1RB#24




Band66_5MHz_QPSK_132647_25RB#0




Band66_5MHz_16QAM_131997_1RB#0




Band66_5MHz_16QAM_131997_1RB#24




Band66_5MHz_16QAM_131997_25RB#0




Band66_5MHz_16QAM_132647_1RB#0




Band66_5MHz_16QAM_132647_1RB#24




Band66_5MHz_16QAM_132647_25RB#0




Band66_5MHz_64QAM_131997_1RB#0




Band66_5MHz_64QAM_131997_1RB#24



Band66_5MHz_64QAM_131997_25RB#0




Band66_5MHz_64QAM_132647_1RB#0




Band66_5MHz_64QAM_132647_1RB#24







Band66_10MHz_QPSK_132622_1RB#0




Band66_10MHz_QPSK_132622_1RB#49




Band66_10MHz_QPSK_132622_50RB#0




Band66_10MHz_16QAM_132022_1RB#0




Band66_10MHz_16QAM_132022_1RB#49




Band66_10MHz_16QAM_132022_50RB#0




Band66_10MHz_16QAM_132622_1RB#0




Band66_10MHz_16QAM_132622_1RB#49




Band66_10MHz_16QAM_132622_50RB#0




Band66_10MHz_64QAM_132022_1RB#0




Band66_10MHz_64QAM_132022_1RB#49




Band66_10MHz_64QAM_132022_50RB#0




Band66_10MHz_64QAM_132622_1RB#0




Band66_10MHz_64QAM_132622_1RB#49




Band66_10MHz_64QAM_132622_50RB#0




Band66_15MHz_QPSK_132047_1RB#0




Band66_15MHz_QPSK_132047_1RB#74




Band66_15MHz_QPSK_132047_75RB#0




Band66_15MHz_QPSK_132597_1RB#0




Band66_15MHz_QPSK_132597_1RB#74









Band66_15MHz_64QAM_132047_1RB#74




Band66_15MHz_64QAM_132047_75RB#0




Band66_15MHz_64QAM_132597_1RB#0




Band66_15MHz_64QAM_132597_1RB#74




Band66_15MHz_64QAM_132597_75RB#0



Band66_20MHz_QPSK_132072_1RB#0



Band66_20MHz_QPSK_132072_1RB#99



Band66_20MHz_QPSK_132072_100RB#0