


Intertek Report No.: 231204042SZN-005_Appendix C


Display



Band66-3MHz-16QAM-131987-15RB#0

Connection Established


RRC State: Connected




Band66-3MHz-16QAM-132322-15RB#0




Display






DI




Band66-5MHz-QPSK-132322-25RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band66-5MHz-QPSK-132647-25RB#0




Band66-5MHz-16QAM-131997-25RB#0




Band66-5MHz-16QAM-132322-25RB#0




Intertek Report No.: 231204042SZN-005_Appendix C






Band66-10MHz-QPSK-132022-50RB#0




Band66-10MHz-QPSK-132322-50RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band66-10MHz-QPSK-132622-50RB#0




Band66-10MHz-16QAM-132022-50RB#0




Band66-10MHz-16QAM-132322-50RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band66-10MHz-16QAM-132622-50RB#0




Band66-15MHz-QPSK-132047-75RB#0




Band66-15MHz-QPSK-132322-75RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band66-15MHz-QPSK-132597-75RB#0




Band66-15MHz-16QAM-132047-75RB#0




Band66-15MHz-16QAM-132322-75RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band66-15MHz-16QAM-132597-75RB#0




Band66-20MHz-QPSK-132072-100RB#0




Band66-20MHz-QPSK-132322-100RB#0




Intertek Report No.: 231204042SZN-005_Appendix C






Band66-20MHz-16QAM-132072-100RB#0




Band66-20MHz-16QAM-132322-100RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band66-20MHz-16QAM-132572-100RB#0



Band71-5MHz-QPSK-133147-25RB#0



Band71-5MHz-QPSK-133297-25RB#0