

PHOTOS EXHIBIT

Report Number: R13156676-EP1

Applicant: Hunter Industries

1940 Diamond Street

San Marcos, CA 92078-5120 USA

Model: BTT-100/101

Contains FCC ID : M3UBTT1

Contains IC: 2772A-BTT1

EUT Description: Water Timer

Test Standard(s): FCC 47 CFR PART 15 SUBPART C

ISED RSS-247 ISSUE 2

ISED RSS-GEN ISSUE 5 + AMD 1

Date Of Issue:

2020-11-06

Prepared by:

UL LLC

12 Laboratory Dr.

Research Triangle Park, NC 27709 U.S.A.

TEL: (919) 549-1400



DATE: 2020-11-06 CONTAINS IC: 2772A-BTT1


REPORT REVISION HISTORY

| Rev. | Issue Date | Revisions | Revised By |
|------|---------------|---------------|-------------|
| 1 | 2020-11-06 | Initial Issue | Mike Antola |

TABLE OF CONTENTS


| RE | PORT REVISION HISTORY | 2 |
|-----|-----------------------|---|
| TAI | BLE OF CONTENTS | 3 |
| 1. | SETUP DIAGRAMS | 4 |
| 2 | SETUD PHOTOS | 5 |

1. SETUP DIAGRAMS





2. SETUP PHOTOS


CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP














DATE: 2020-11-06 CONTAINS IC: 2772A-BTT1

END OF PHOTOS EXHIBIT