





Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: B4305
Test: 211230
Test to: CFR47 15C, RSS-247
File: B4305 Short Term Conf TSup


SN's: 2571389580, 1786939084
FCC ID: IPH-B4305
IC: 1792A-B4305
Date: March 10, 2022
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: B4305
Test: 211230
Test to: CFR47 15C, RSS-247
File: B4305 Short Term Conf TSup


SN's: 2571389580, 1786939084
FCC ID: IPH-B4305
IC: 1792A-B4305
Date: March 10, 2022
Page 2 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: B4305
Test: 211230
Test to: CFR47 15C, RSS-247
File: B4305 Short Term Conf TSup

SN's: 2571389580, 1786939084
FCC ID: IPH-B4305
IC: 1792A-B4305
Date: March 10, 2022
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: B4305
Test: 211230
Test to: CFR47 15C, RSS-247
File: B4305 Short Term Conf TSup

SN's: 2571389580, 1786939084
FCC ID: IPH-B4305
IC: 1792A-B4305
Date: March 10, 2022
Page 4 of 4