



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 13.DEC.2021 18:05:13

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 13.DEC.2021 18:05:32

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 13.DEC.2021 18:05:47

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 13.DEC.2021 18:06:05

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 13.DEC.2021 18:06:20

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 13.DEC.2021 18:06:41

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 13.DEC.2021 18:06:57

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 13.DEC.2021 18:07:14

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 13.DEC.2021 18:07:33

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 13.DEC.2021 18:07:56

Band 2_3 MHz_High_QPSK_RB15#0




Date: 13.DEC.2021 18:08:14

Band 2_3 MHz_High_16QAM_RB15#0




Date: 13.DEC.2021 18:08:35

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 13.DEC.2021 18:08:57

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 13.DEC.2021 18:09:15

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 13.DEC.2021 18:09:30

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 13.DEC.2021 18:09:44

Band 2_5 MHz_High_QPSK_RB25#0




Date: 13.DEC.2021 18:09:59

Band 2_5 MHz_High_16QAM_RB25#0




Date: 13.DEC.2021 18:10:20

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 13.DEC.2021 18:10:43

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 13.DEC.2021 18:11:08

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 13.DEC.2021 18:11:37

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 13.DEC.2021 18:12:01

Band 2_10 MHz_High_QPSK_RB50#0




Date: 13.DEC.2021 18:12:27

Band 2_10 MHz_High_16QAM_RB50#0




Date: 13.DEC.2021 18:12:52

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 13.DEC.2021 18:13:17

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 13.DEC.2021 18:13:41

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 13.DEC.2021 18:14:03

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 13.DEC.2021 18:14:33

Band 2_15 MHz_High_QPSK_RB75#0




Date: 13.DEC.2021 18:15:07

Band 2_15 MHz_High_16QAM_RB75#0




Date: 13.DEC.2021 18:15:34

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 13.DEC.2021 18:16:06

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 13.DEC.2021 18:16:33

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 13.DEC.2021 18:17:11

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 13.DEC.2021 18:17:37

Band 2_20 MHz_High_QPSK_RB100#0




Date: 13.DEC.2021 18:18:12

Band 2_20 MHz_High_16QAM_RB100#0




Date: 13.DEC.2021 18:18:47

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 13.DEC.2021 18:19:07

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 13.DEC.2021 18:19:23

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 13.DEC.2021 18:19:38

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 13.DEC.2021 18:19:53

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 13.DEC.2021 18:20:11

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 13.DEC.2021 18:20:29

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 13.DEC.2021 18:20:48

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 13.DEC.2021 18:21:03

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 13.DEC.2021 18:21:22

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 13.DEC.2021 18:21:37

Band 4_3 MHz_High_QPSK_RB15#0




Date: 13.DEC.2021 18:21:55

Band 4_3 MHz_High_16QAM_RB15#0




Date: 13.DEC.2021 18:22:13

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 13.DEC.2021 18:22:35

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 13.DEC.2021 18:22:53

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 13.DEC.2021 18:23:11

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 13.DEC.2021 18:23:28

Band 4_5 MHz_High_QPSK_RB25#0




Date: 13.DEC.2021 18:23:50

Band 4_5 MHz_High_16QAM_RB25#0




Date: 13.DEC.2021 18:24:04

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 13.DEC.2021 18:24:31

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 13.DEC.2021 18:24:56

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 13.DEC.2021 18:25:22

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 13.DEC.2021 18:25:47

Band 4_10 MHz_High_QPSK_RB50#0



Date: 13.DEC.2021 18:26:19

Band 4_10 MHz_High_16QAM_RB50#0




Date: 13.DEC.2021 18:26:50

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 13.DEC.2021 18:27:22

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 13.DEC.2021 18:27:47

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 13.DEC.2021 18:28:15

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 13.DEC.2021 18:28:39

Band 4_15 MHz_High_QPSK_RB75#0




Date: 13.DEC.2021 18:29:07

Band 4_15 MHz_High_16QAM_RB75#0




Date: 13.DEC.2021 18:29:34

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 13.DEC.2021 18:30:03

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 13.DEC.2021 18:30:33

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 13.DEC.2021 18:31:16

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 13.DEC.2021 18:31:44

Band 4_20 MHz_High_QPSK_RB100#0




Date: 13.DEC.2021 18:32:08

Band 4_20 MHz_High_16QAM_RB100#0




Date: 13.DEC.2021 18:32:36

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 13.DEC.2021 18:32:52

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 13.DEC.2021 18:33:10

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 13.DEC.2021 18:33:25

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 13.DEC.2021 18:33:40

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 13.DEC.2021 18:33:58

Band 5 1.4 MHz High 16QAM RB6#0




Date: 13.DEC.2021 18:34:19

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 13.DEC.2021 18:34:38

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 13.DEC.2021 18:34:53

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 13.DEC.2021 18:35:11

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 13.DEC.2021 18:35:26

Band 5_3 MHz_High_QPSK_RB15#0




Date: 13.DEC.2021 18:35:44

Band 5_3 MHz_High_16QAM_RB15#0




Date: 13.DEC.2021 18:36:05

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 13.DEC.2021 18:36:27

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 13.DEC.2021 18:36:48

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 13.DEC.2021 18:37:06

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 13.DEC.2021 18:37:30

Band 5_5 MHz_High_QPSK_RB25#0




Date: 13.DEC.2021 18:37:48

Band 5_5 MHz_High_16QAM_RB25#0




Date: 13.DEC.2021 18:38:02

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 13.DEC.2021 18:38:29

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 13.DEC.2021 18:38:54

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 13.DEC.2021 18:39:23

Band 5 10 MHz Middle 16QAM RB50#0




Date: 13.DEC.2021 18:39:45

Band 5_10 MHz_High_QPSK_RB50#0




Date: 13.DEC.2021 18:40:07

Band 5_10 MHz_High_16QAM_RB50#0




Date: 13.DEC.2021 18:40:32

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 13.DEC.2021 18:40:48

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 13.DEC.2021 18:41:05

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 13.DEC.2021 18:41:24

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 13.DEC.2021 18:41:41

Band 7_5 MHz_High_QPSK_RB25#0




Date: 13.DEC.2021 18:41:59

Band 7_5 MHz_High_16QAM_RB25#0




Date: 13.DEC.2021 18:42:23

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 13.DEC.2021 18:42:47

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 13.DEC.2021 18:43:15

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 13.DEC.2021 18:43:47

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 13.DEC.2021 18:44:15

Band 7_10 MHz_High_QPSK_RB50#0




Date: 13.DEC.2021 18:44:37

Band 7_10 MHz_High_16QAM_RB50#0




Date: 13.DEC.2021 18:44:59

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 13.DEC.2021 18:45:33

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 13.DEC.2021 18:46:06

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 13.DEC.2021 18:46:34

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 13.DEC.2021 18:47:01

Band 7_15 MHz_High_QPSK_RB75#0




Date: 13.DEC.2021 18:47:23

Band 7_15 MHz_High_16QAM_RB75#0




Date: 13.DEC.2021 18:47:47

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 13.DEC.2021 18:48:19

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 13.DEC.2021 18:48:49

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 13.DEC.2021 18:49:14

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 13.DEC.2021 18:49:44

Band 7_20 MHz_High_QPSK_RB100#0




Date: 13.DEC.2021 18:50:15

Band 7 20 MHz High 16QAM RB100#0




Date: 13.DEC.2021 18:50:46

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 14.DEC.2021 09:20:36

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 14.DEC.2021 09:20:53

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 14.DEC.2021 09:21:18

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 14.DEC.2021 09:21:36

Band 38_5 MHz_High_QPSK_RB25#0




Date: 14.DEC.2021 09:21:53

Band 38_5 MHz_High_16QAM_RB25#0




Date: 14.DEC.2021 09:22:11

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 14.DEC.2021 09:22:38

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 14.DEC.2021 09:23:02

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 14.DEC.2021 09:23:25

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 14.DEC.2021 09:23:50

Band 38_10 MHz_High_QPSK_RB50#0




Date: 14.DEC.2021 09:24:09

Band 38_10 MHz_High_16QAM_RB50#0




Date: 14.DEC.2021 09:24:37

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 14.DEC.2021 09:25:05

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 14.DEC.2021 09:25:39

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 14.DEC.2021 09:26:10

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 14.DEC.2021 09:26:40

Band 38_15 MHz_High_QPSK_RB75#0




Date: 14.DEC.2021 09:27:10

Band 38_15 MHz_High_16QAM_RB75#0




Date: 14.DEC.2021 09:27:38

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 14.DEC.2021 09:28:06

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 14.DEC.2021 09:28:40

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 14.DEC.2021 09:29:11

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 14.DEC.2021 09:29:31

Band 38_20 MHz_High_QPSK_RB100#0




Date: 14.DEC.2021 09:29:59

Band 38_20 MHz_High_16QAM_RB100#0




Date: 14.DEC.2021 09:30:29

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 14.DEC.2021 10:38:40

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 14.DEC.2021 10:38:58

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 14.DEC.2021 10:39:19

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 14.DEC.2021 10:39:43

Band 41_5 MHz_High_QPSK_RB25#0




Date: 14.DEC.2021 10:40:04

Band 41_5 MHz_High_16QAM_RB25#0




Date: 14.DEC.2021 10:40:21

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 14.DEC.2021 10:40:44

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 14.DEC.2021 10:41:09

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 14.DEC.2021 10:41:35

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 14.DEC.2021 10:41:59

Band 41_10 MHz_High_QPSK_RB50#0




Date: 14.DEC.2021 10:42:25

Band 41_10 MHz_High_16QAM_RB50#0




Date: 14.DEC.2021 10:42:50

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 14.DEC.2021 10:43:22

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 14.DEC.2021 10:43:49

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 14.DEC.2021 10:44:26

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 14.DEC.2021 10:44:50

Band 41_15 MHz_High_QPSK_RB75#0




Date: 14.DEC.2021 10:45:18

Band 41_15 MHz_High_16QAM_RB75#0




Date: 14.DEC.2021 10:45:45

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 14.DEC.2021 10:46:13

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 14.DEC.2021 10:46:43

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 14.DEC.2021 10:47:11

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 14.DEC.2021 10:47:41

Band 41_20 MHz_High_QPSK_RB100#0



Date: 14.DEC.2021 10:48:15

Band 41_20 MHz_High_16QAM_RB100#0



Date: 14.DEC.2021 10:48:52