FCC ID: EHACWAN-RIM902 REPORT NO: 990824-1 Page 1 of 4

MEASUREMENT/TECHNICAL REPORT



Intermec Technologies Corporation Cellular Radio Module OEM From RIM 902

REPORT NO: 990824-1

DATE: August 24, 1999

APPENDIX D


TYPICAL USE PHOTOGRAPHS

FCC ID: EHACWAN-RIM902 REPORT NO: 990824-1 Page 2 of 4

Photo 1: Shows the right-hand user during normal operation.



Photo 2: Shows the left-hand user during normal operation.



FCC ID: EHACWAN-RIM902 REPORT NO: 990824-1 Page 3 of 4

Photo 3: Shows the tablet computer while carried by the hand-strap, transmitter in standby.



Photo 4: Shows possible holding while transmitter is in standby, 0.2mS TX once every 10 minutes.



FCC ID: EHACWAN-RIM902 REPORT NO: 990824-1 Page 4 of 4






Photo 6: Shows another typical installation within a utility truck.

