

INTERTEK TESTING SERVICE

Report No: 15071281HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: GMR3055-2CK



INTERTEK TESTING SERVICE

Report No: 15071281HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Model: GMR3055-2CK



INTERTEK TESTING SERVICE


Report No: 15071281HKG-001

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)

Model: GMR3055-2CK



INTERTEK TESTING SERVICE


Report No: 15071281HKG-001

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Rear View)

Model: GMR3055-2CK



INTERTEK TESTING SERVICE

Report No: 15071281HKG-001

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Side View)

Model: GMR3055-2CK

