

Page: 49 of 109



Port2_10M_3555MHz_TM1.1_CHL_CSE0b



Port2_10M_3555MHz_TM1.1_CHL_CSE2





Port2_10M_3555MHz_TM1.1_CHL_CSE1



Port2_10M_3555MHz_TM1.1_CHL_CSE3







Page: 50 of 109

Port2_10M_3555MHz_TM1.1_CHL_CSEpart96



Port2_10M_3624.99MHz_TM1.1_CHM_CSE0b



Port2_10M_3624.99MHz_TM1.1_CHM_CSE2



Port2_10M_3624.99MHz_TM1.1_CHM_CSE0a



Port2_10M_3624.99MHz_TM1.1_CHM_CSE1



Port2_10M_3624.99MHz_TM1.1_CHM_CSE3





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-Conditions/Terms-and-Conditions/Terms-and-Enditions/Terms-and-Conditions/Terms-and-Enditions/Terms-and-Condit



Page: 51 of 109

Port2_10M_3624.99MHz_TM1.1_CHM_CSEpart 96

Port2_10M_3694.98MHz_TM1.1_CHH_CSE0a



Port2_10M_3694.98MHz_TM1.1_CHH_CSE0b



Port2_10M_3694.98MHz_TM1.1_CHH_CSE1



Port2_10M_3694.98MHz_TM1.1_CHH_CSE2



Port2_10M_3694.98MHz_TM1.1_CHH_CSE3







Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic foraut documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-Conditions/Terms-and-Cond



Page: 52 of 109



Port2_20M_3560.01MHz_TM1.1_CHL_CSE0b



Port2_20M_3560.01MHz_TM1.1_CHL_CSE2





Port2_20M_3560.01MHz_TM1.1_CHL_CSE1



Port2_20M_3560.01MHz_TM1.1_CHL_CSE3








Page: 53 of 109

Port2_20M_3560.01MHz_TM1.1_CHL_CSEpart9 Port2 6

Port2_20M_3624.99MHz_TM1.1_CHM_CSE0a



Port2_20M_3624.99MHz_TM1.1_CHM_CSE0b



Port2_20M_3624.99MHz_TM1.1_CHM_CSE1



Port2_20M_3624.99MHz_TM1.1_CHM_CSE2



Port2_20M_3624.99MHz_TM1.1_CHM_CSE3









Page: 54 of 109

Port2_20M_3624.99MHz_TM1.1_CHM_CSEpart 96

Port2_20M_3690MHz_TM1.1_CHH_CSE0b



Port2_20M_3690MHz_TM1.1_CHH_CSE2



Port2_20M_3690MHz_TM1.1_CHH_CSE0a



Port2_20M_3690MHz_TM1.1_CHH_CSE1



Port2_20M_3690MHz_TM1.1_CHH_CSE3








Page: 55 of 109

Port2_20M_3690MHz_TM1.1_CHH_CSEpart96



Port2_30M_3565.02MHz_TM1.1_CHL_CSE0b



Port2_30M_3565.02MHz_TM1.1_CHL_CSE2



Port2_30M_3565.02MHz_TM1.1_CHL_CSE0a



Port2_30M_3565.02MHz_TM1.1_CHL_CSE1



Port2_30M_3565.02MHz_TM1.1_CHL_CSE3





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/T



Page: 56 of 109

Port2_30M_3565.02MHz_TM1.1_CHL_CSEpart9 Po

Port2_30M_3624.99MHz_TM1.1_CHM_CSE0a



Port2_30M_3624.99MHz_TM1.1_CHM_CSE0b



Port2_30M_3624.99MHz_TM1.1_CHM_CSE1



Port2_30M_3624.99MHz_TM1.1_CHM_CSE2



Port2_30M_3624.99MHz_TM1.1_CHM_CSE3







Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document advised that information contained hereon reflects the Company's findings at the time of its intervition only and within the limits of Client's Instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced attraction, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) are retained for 30 days only.

Attention: Co-leack the authenticity of testing imspection reports a certificate, please contact us at telephone: (86-75)83071443, **Attention:** Co-leack the authenticity of testing imspection reports a certificate, please contact us at telephone: (86-75)83071443, **Termines** or the supplementation of the supplemen



Page: 57 of 109

Port2_30M_3624.99MHz_TM1.1_CHM_CSEpart 96

Port2_30M_3684.99MHz_TM1.1_CHH_CSE0a



Port2_30M_3684.99MHz_TM1.1_CHH_CSE0b



Port2_30M_3684.99MHz_TM1.1_CHH_CSE2



Figure 20.0 Seems on the process of the process of

Port2_30M_3684.99MHz_TM1.1_CHH_CSE1



Port2_30M_3684.99MHz_TM1.1_CHH_CSE3





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic foraut documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-Conditions/Terms-and-Cond



Page: 58 of 109



Port2_40M_3570MHz_TM1.1_CHL_CSE0b



Port2_40M_3570MHz_TM1.1_CHL_CSE2





Port2_40M_3570MHz_TM1.1_CHL_CSE1



Port2_40M_3570MHz_TM1.1_CHL_CSE3





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-a-Document.aspx. Attention is drawn to the limitation of liability indemnification and jurisdiction issues defined therein. Any holder of this document sadvised that information contained hereon reflects the Company indings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company, Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: On check the authenticity of testing imspection report 3 certificate, please contact us at telephone: (86-75) 8307 1443, **Attention**: On check the authenticity of testing imspection report 3 certificate, please contact us at telephone: (86-75) 8307 1443, **Termination**: The contact of the conta



Page: 59 of 109

Port2_40M_3570MHz_TM1.1_CHL_CSEpart96



Port2_40M_3624.99MHz_TM1.1_CHM_CSE0b



Port2_40M_3624.99MHz_TM1.1_CHM_CSE2



Port2_40M_3624.99MHz_TM1.1_CHM_CSE0a



Port2_40M_3624.99MHz_TM1.1_CHM_CSE1



Port2_40M_3624.99MHz_TM1.1_CHM_CSE3





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic Document aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document advised that information contained hereon reflects the Company's findings at the time of its intervition only and within the limits of Client's instructions, if any. The Company's osle responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document. Show document cannot be reproduced so that the company's findings at the transaction from exercising all their rights and obligations under the transaction document. Show the comment of the content or repair as of this document is unlawful and offender may be prosecuted to the fullest extend of the which the content or repairs to the content of the



Page: 60 of 109

Port2_40M_3624.99MHz_TM1.1_CHM_CSEpart 96

THE PART OF THE PA

Port2_40M_3679.98MHz_TM1.1_CHH_CSE0b

.:: 🦠



Port2_40M_3679.98MHz_TM1.1_CHH_CSE2




Port2_40M_3679.98MHz_TM1.1_CHH_CSE0a



Port2_40M_3679.98MHz_TM1.1_CHH_CSE1



Port2_40M_3679.98MHz_TM1.1_CHH_CSE3







Page: 61 of 109

Port2_40M_3679.98MHz_TM1.1_CHH_CSEpart9 6



