FCC TEST REPORT Report No.: F391202

1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. FCC ID : JCK-GN-BTP01 TEL: 886-2-2696-2468 Page No. : 1 of 3

FAX: 886-2-2696-2255 | Issued : Oct. 06, 2003

FCC TEST REPORT Report No.: F391202



SIDE VIEW


FCC ID : JCK-GN-BTP01 SPORTON International Inc.

Page No. : 2 of 3 Issued : Oct. 06, 2003 TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC TEST REPORT Report No.: F391202

1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 FCC ID
 : JCK-GN-BTP01

 TEL: 886-2-2696-2468
 Page No. : 3 of 3